Marks Gamer Well Status Report

CAVE POOL UNIT

е	и
ā	ø
2	:
4	P
•	_
•	
4	_
7	-
Ļ	J
•	
e	-
2	Ξ
ς	
_	3
_	

44411 140. 00 I				
Status	Inspect Date	Violation?	Comments	API Number
A	1/30/2001	Yes	No Pumping Unit. Tubing out of hole.	30015027840000
Well No. 003				
Status	Inspect Date	Violation?	Comments	API Number
S	6/15/2001	Yes	No Pumping Unit.	30015028920000
S	1/30/2001	Zo	No Pumping Unit.	30015028920000
Well No. 010				
Status	Inspect Date	Violation?	Comments	API Number
Α	6/12/2001	No	A-OK. All Equipment and Location in Good Shape.	30015009930000
Α	1/30/2001	Yes	Location needs attention. Equipment OK. STUFFING BOX LEAKING OIL	30015009930000
Well No. 012				
Status	Inspect Date	Violation?	Comments	API Number
A	1/30/2001	Z _o	No Electric Hook-up.	30015028800000
A	6/12/2001	Yes	No Electric Hook-up. Photo	30015028800000
Well No. 014	-			
Status	Inspect Date	Violation?	Comments	API Number

OCD EMICI NO. 14

Caso % 12757

1/30/2001 Yes No Pumping Unit. NO FLOWLINE. Photo	30015029060000	P/A	Z :	1/30/2001	p ·
1/30/2001 Yes 10/16/2001 No Inspect Date Violation? 1/30/2001 Yes 6/12/2001 Yes 10/16/2001 No Inspect Date Violation? 1/30/2001 No 1/30/2001 No 6/12/2001 No 6/12/2001 Yes Inspect Date Violation? 1/30/2001 Yes	1	P/A-Location cle	No	10/16/2001	P
1/30/2001 Yes No Pumping Unit. NO FLOWLINE. Photo 10/16/2001 No No Pumping Unit. NO FLOWLINE. Photo 1/30/2001 Yes No Pumping Unit. No approval to T/A well. No flowline. No well sign. 1/30/2001 Yes No Pumping Unit. No approval to T/A well. No flowline. No well sign. 1/30/2001 No No Pumping Unit. No approval to T/A well. No flowline. No well sign. 1/30/2001 No No Pumping Unit. No approval to T/A well. No flowline. No well sign. 1/30/2001 No P/A LOCATION CLEAN. Photo 1/30/2001 No P/A LOCATION CLEAN. Photo 1/30/2001 No No Motor on Pumping Unit. Photo 1/30/2001 Yes No Pumping Unit. Photo 1/30/2001 Yes No Pumping Unit. Photo			Violation	Inspect Date	Status
1/30/2001 Yes No Pumping Unit. NO FLOWLINE. Photo 10/16/2001 No No Pumping Unit. NO FLOWLINE. Photo Inspect Date Violation? Comments 1/30/2001 Yes No Pumping Unit. No approval to T/A well. No flowline. No well sign. 6/12/2001 Yes No Pumping Unit. No approval to T/A well. No flowline. No well sign. 10/16/2001 No Pumping Unit. No approval to T/A well. No flowline. No well sign. Inspect Date Violation? Comments 1/30/2001 No P/A LOCATION CLEAN. Photo Inspect Date Violation? Comments 1/30/2001 No No Motor on Pumping Unit. Photo 1/30/2001 No No Motor on Pumping Unit. Photo				•	Well No. 022
Inspect Date Violation? Comments I/30/2001 No Pumping Unit. NO FLOWLINE. Photo I/30/2001 Yes No Pumping Unit. No approval to T/A well. No flowline. No well sign. I/30/2001 Yes No Pumping Unit. No approval to T/A well. No flowline. No well sign. I/30/2001 No Pumping Unit. No approval to T/A well. No flowline. No well sign. I/30/2001 No P/A LOCATION CLEAN. Photo I/30/2001 No P/		No Pumping Unit. Photo	Yes	6/12/2001	A
1/30/2001 Yes No Pumping Unit. NO FLOWLINE. Photo 10/16/2001 No No Pumping Unit. NO FLOWLINE. Photo Inspect Date Violation? Comments 1/30/2001 Yes No Pumping Unit. No approval to T/A well. No flowline. No well sign. Idle Well 10/16/2001 No No Pumping Unit. No approval to T/A well. No flowline. No well sign. Idle Well Inspect Date Violation? Comments 1/30/2001 No P/A LOCATION CLEAN. Photo Inspect Date Violation? Comments Inspect Date Violation? Comments Inspect Date Violation? Comments	t as	No Motor on Pumping Unit.	No	1/30/2001	Α
1/30/2001 Yes No Pumping Unit. NO FLOWLINE. Photo 10/16/2001 No No Pumping Unit. NO FLOWLINE. Photo Inspect Date Violation? Comments 1/30/2001 Yes No Pumping Unit. No approval to T/A well. No flowline. No well sign. Idle Well 10/16/2001 Yes No Pumping Unit. No approval to T/A well. No flowline. No well sign. Idle Well. Photo Inspect Date Violation? Comments 1/30/2001 No P/A LOCATION CLEAN. Photo 10/16/2001 No P/A LOCATION CLEAN. Photo		A CONTRACTOR OF THE CONTRACTOR	Violation	Inspect Date	Status
1/30/2001 Yes No Pumping Unit. NO FLOWLINE. Photo 10/16/2001 No No Pumping Unit. NO FLOWLINE. Photo Inspect Date Violation? Comments 1/30/2001 Yes No Pumping Unit. No approval to T/A well. No flowline. No well sign. 6/12/2001 Yes No Pumping Unit. No approval to T/A well. No flowline. No well sign. 1/0/16/2001 No No Pumping Unit. No approval to T/A well. No flowline. No well sign. Inspect Date Violation? Comments 1/30/2001 No P/A LOCATION CLEAN. Photo					Well No. 019
1/30/2001 Yes No Pumping Unit. NO FLOWLINE. Photo 10/16/2001 No No Pumping Unit. NO FLOWLINE. Photo Inspect Date Violation? Comments 1/30/2001 Yes No Pumping Unit. No approval to T/A well. No flowline. No well sign. 1/0/16/2001 No No Pumping Unit. No approval to T/A well. No flowline. No well sign. 1/0/16/2001 No No Pumping Unit. No approval to T/A well. No flowline. No well sign. Inspect Date Violation? Comments 1/30/2001 No P/A LOCATION CLEAN. Photo	30015028930000	P/A LOCATION CLEAN. Photo	N _o	10/16/2001	Р
1/30/2001 Yes No Pumping Unit. NO FLOWLINE. Photo 10/16/2001 No No Pumping Unit. NO FLOWLINE. Photo Inspect Date Violation? Comments 1/30/2001 Yes No Pumping Unit. No approval to T/A well. No flowline. No well sign. 6/12/2001 Yes No Pumping Unit. No approval to T/A well. No flowline. No well sign. 10/16/2001 No No Pumping Unit. No approval to T/A well. No flowline. No well sign. 10/16/2001 No No Pumping Unit. No approval to T/A well. No flowline. No well sign. Inspect Date Violation? Comments	30015028930000	P/A LOCATION CLEAN. Photo	Z o	1/30/2001	P
1/30/2001 Yes No Pumping Unit. NO FLOWLINE. Photo 10/16/2001 No No Pumping Unit. NO FLOWLINE. Photo Inspect Date Violation? Comments 1/30/2001 Yes No Pumping Unit. No approval to T/A well. No flowline. No well sign. 6/12/2001 Yes No Pumping Unit. No approval to T/A well. No flowline. No well sign. 10/16/2001 No No Pumping Unit. No approval to T/A well. No flowline. No well sign. 10/16/2001 No No Pumping Unit. No approval to T/A well. No flowline. No well sign.			Violation	Inspect Date	Status
1/30/2001 Yes No Pumping Unit. NO FLOWLINE. Photo 10/16/2001 No No Pumping Unit. NO FLOWLINE. Photo Inspect Date Violation? Comments 1/30/2001 Yes No Pumping Unit. No approval to T/A well. No flowline. No well sign. 6/12/2001 Yes No Pumping Unit. No approval to T/A well. No flowline. No well sign. 10/16/2001 No No Pumping Unit. No approval to T/A well. No flowline. No well sign. 10/16/2001 No No Pumping Unit. No approval to T/A well. No flowline. No well sign.					Well No. 017
1/30/2001 Yes No Pumping Unit. NO FLOWLINE. Photo 10/16/2001 No No Pumping Unit. NO FLOWLINE. Photo Inspect Date Violation? Comments 1/30/2001 Yes No Pumping Unit. No approval to T/A well. No flowline. No well sign. 6/12/2001 Yes Idle Well	30015028750000	No Pumping Unit. No approval to T/A well. No flowline. No well sign. Idle Well. Photo	N _o	10/16/2001	7
1/30/2001 Yes No Pumping Unit. NO FLOWLINE. Photo 10/16/2001 No No Pumping Unit. NO FLOWLINE. Photo Inspect Date Violation? Comments 1/30/2001 Yes No Pumping Unit. No approval to T/A well. No flowline. No well sign.	30015028750000	No Pumping Unit. No approval to T/A well. No flowline. No well sign. Idle Well	Yes	6/12/2001	Н
1/30/2001 Yes No Pumping Unit. NO FLOWLINE. Photo 10/16/2001 No No Pumping Unit. NO FLOWLINE. Photo Inspect Date Violation? Comments	30015028750000	No Pumping Unit. No approval to T/A well. No flowline. No well sign.	Yes	1/30/2001	Т
1/30/2001 Yes No Pumping Unit. NO FLOWLINE. Photo 10/16/2001 No No Pumping Unit. NO FLOWLINE. Photo		AND THE CONTRACTOR CONTRACTOR AND	Violation	Inspect Date	Status
1/30/2001 Yes No Pumping Unit. NO FLOWLINE. Photo 10/16/2001 No No Pumping Unit. NO FLOWLINE. Photo					Well No. 016
1/30/2001 Yes No Pumping Unit. NO FLOWLINE. Photo	ω	No Pumping Unit. NO FLOWLINE. Photo	N _o	10/16/2001	S
	30015028810000	No Pumping Unit. NO FLOWLINE. Photo	Yes	1/30/2001	S

	THE PROPERTY OF THE PROPERTY O	######################################			
	Status	Inspect Date	Violation?	Comments	API Number
	>	10/31/2001	Yes	Well sign lists operator as Frostman Oil Corp. Violation Rule 103. Contamination @ wellhead needs clean-up.	30015029020000
	A	11/15/2001	No	A-OK. All Equipment and Location in Good Shape.	30015029020000
	>	1/30/2001	Yes	Location needs attention. Equipment OK. OIL IN CELLAR.	30015029020000
<u>₹</u>	Well No. 026				
	Status	Inspect Date	Violation?	Comments	API Number
	Α	6/11/2001	No	No Motor on Pumping Unit. PHOTO(DISK 1)	30015029040000
€	Well No. 027				
	Status	Inspect Date	Violation?	Comments	API Number
	A	10/16/2001	N _o	No Well Sign. Photo	30015028970000
	A	2/12/2001	Yes	Photos taken of Area	30015028970000
	>	3/6/2001	N _o	All OK. All Equipment and Location in Good Shape.	30015028970000
	A	2/27/2001	Yes	Injection line leaking. hole in tubing. WELL MUST BE SHUTIN PENDING TUBING REPAIR.	30015028970000
¥e	Well No. 028				
	Status	Inspect Date	Violation?	Comments	API Number
	Α	2/13/2001	No	No Motor on Pumping Unit.	30015028870000
¥	Well No. 030				
	Status	Inspect Date	Violation?	Comments	API Number

T 12/3/2001 No SET CIBP @2300' PRESS. TEST START 520# STOP 490# 30	T 10/16/2001 No No FI	T 2/12/2001 Yes No FI	Status Inspect Date Violation?	Well No. 041	A 3/6/2001 No Equip	A 6/11/2001 Yes No re	Status Inspect Date Violation?	Well No. 036	A 6/11/2001 No A-OK	Status Inspect Date Violation?	Well No. 035	S 1/30/2001 Yes No Pu	S 10/16/2001 No No Pu	Status Inspect Date Violation?	Well No. 032	S 1/30/2001 No No M	S 6/15/2001 Yes No M
	No Flowline. Photo	No Flowline. Photo	Comments		Equipment sub-standard. Replace ASAP. Unable to open bradenhead valve	No repairs have been made to bradenhead valve. Unable to open.			A-OK. All Equipment and Location in Good Shape.			No Pumping Unit. NO FLOWLINE	No Pumping Unit. NO FLOWLINE. Photo	Comments		No Motor on Pumping Unit.	No Motor on Pumping Unit.
2001202720000	2001 50202 5000	30015029260000	API Number		30015029150000	30015029150000	API Number		30015029140000	API Number		30015029270000	30015029270000	API Number		30015028910000	30015028910000

			Wel						Well			Wel				بد	Well		
	>	Status	Well No. 059	H	\dashv	Н	Н	Status	Well No. 053	A	Status	Well No. 052	-	Н	_	Status	Well No. 051	Н	
Ē	6/11/2001	Inspect Date	_	11/16/2001	10/16/2001	1/31/2001	3/6/2001	Inspect Date		2/12/2001	Inspect Date		11/16/2001	3/6/2001	1/31/2001	Inspect Date		11/30/2001	
	Z °	Violation?		S S	N _o	N _o	Yes	Violation?		N _o	Violation?		S Z	Yes	Yes	Violation?		Z	
	No Motor on Pumping Unit. PHOTO(DISK 1)			START TEST 540# END TEST 10 MIN. 360#	Photos taken of Area	No Flowline.	No Flowline. TA status expired 5/1/95	Comments		All OK. All Equipment and Location in Good Shape.	Comments		PRESS CSG. TO 520# FOR 15 MIN. VALVE BROKE REPLACED VALVE STARTED TEST OVER PRESS. UP TO 520# 30 MIN. END TEST 510 # NO WELL SIGN	Shut-in Letter Sent. Authority to inject withdrawn.	No Well Sign.	Comments		RIG UP TO SPOT 7" CIBP @2300' CAN NOT GET TOOLE IN TO CSG. TRYING TO REMOVE WELL HEAD WAITING ON WELDER	
Page Tr	30015247230000	API Number		30015029120000	30015029120000	30015029120000	30015029120000	API Number		30015029090000	API Number		30015029030000	30015029030000	30015029030000	API Number		30015029260000	

	5
5	Z
000	2000

6/15/2001 No TATE . 001 us Inspect Date Violation? 6/11/2001 Yes . 002 by Inspect Date Violation? 6/11/2001 No 1/13/2001 No
6/15/2001 No nspect Date Violation? 6/11/2001 Yes nspect Date Violation? 6/11/2001 No 2/13/2001 Yes
6/15/2001 No nspect Date Violation? 6/11/2001 Yes 6/11/2001 No

Well No. 004

30015239370000	All OK. All Equipment and Location in Good Shape. B/T	No	2/14/2001	Α
API Number		Violation?	Inspect Date	Status
				Well No. 001
			ON 31 E	DOG CANYON 31 E
30015247600000	Equipment and Location needs minor attention. B/T	N _o	2/13/2001	Α
API Number	Comments	Violation?	Inspect Date	Status
				Well No. 002
30015247590000	No Pumping Unit. Photo	No	6/12/2001	Α
30015247590000	No Pumping Unit. Photo	No	10/16/2001	A
API Number		Violation?	Inspect Date	Status
				Well No. 001
			STATE	DIAMOND STATE
30015247410000	No Net on water tank.	Yes	6/12/2001	Α
API Number		Violation?	Inspect Date	Status
				Well No. 005
30015247420000	No Motor on Pumping Unit. B photo Broken dump line on separator spilling bs&w on ground. Form C-141 required.	Yes	6/12/2001	S
30015247420000	No Motor on Pumping Unit. B	N _o	1/30/2001	S
API Number	Comments	Violation?	Inspect Date	Status
WESTERS DANKENS OF SERVICE SER			A CONTRACTOR OF THE PROPERTY O	

DOG CANYON 36 I STATE Well No. 001

-	_
G	9
7	
	•
_	-

Status	Inspect Date	Violation?	Comments	API Number
Α	2/14/2001	No	All OK. All Equipment and Location in Good Shape. B/T	30015237660000
HODGES FEDERAL	EDERAL			
Well No. 002	.~			
Status	Inspect Date	Violation?	The second secon	API Number
Α	6/11/2001	Yes	No Motor on Pumping Unit. PHOTO(DISK 1) B/T	30015028980000
Α	2/13/2001	No	No Motor on Pumping Unit. B/T	30015028980000
LEVERS				
Well No. 003Y	37			
Status	Inspect Date	Violation?	Comments	API Number
Α	6/12/2001	Yes	Belts off pump unit - motor still running. Photo	30015027870000
Well No. 005				
Status	Inspect Date	Violation?		API Number
Α	1/31/2001	Yes	Valves or other equipment broken. Fix ASAP. STUFFING BOX LEAKING. B/T	30015224430000
Α	6/12/2001	Yes	No action taken on previous violation. STUFFING BOX LEAKING. Photo	30015224430000
Well No. 006	U,			
Status	Inspect Date	Violation?	Comments	API Number

30015248960000	Location needs attention. Equipment OK.	Z	6/12/2001	S
API Number	Comments	Violation?	Inspect Date	Status
				Well No. 002
30015248550000	A-OK. All Equipment and Location in Good Shape. B	N _o	6/11/2001	Α
API Number	Comments	Violation?	Inspect Date	Status
				Well No. 001
			,	RED STATE
30015233410000	Workover unit on location. B/T	No	1/2/2001	S
30015233410000	All OK. All Equipment and Location in Good Shape.	No	2/2/2001	S
API Number		Violation?	Inspect Date	Status
				Well No. 002
		ГАТ	MOSLEY SPRING 32 STAT	MOSLEY SF
30015250910000	All OK. All Equipment and Location in Good Shape.	No	2/14/2001	Α
30015250910000	A-OK. All Equipment and Location in Good Shape.	N _o	6/12/2001	>
API Number	Comments	Violation?	Inspect Date	Status
				Well No. 007
			DERAL	LEVERS FEDERAL
30015230320000	A-OK. All Equipment and Location in Good Shape.	Z	6/12/2001	Α
30015230320000	No Well Sign.	Yes	2/13/2001	Α

		٤					REC V				\{			\$	REC	
>	Status	Well No. 012	H	-	T	Status	ED TWELV	A	Α	Status	Well No. 002	Α	Status	Well No. 001) TWEL	Ω.
1/31/2001	Inspect Date	2	11/30/2001	1/31/2001	10/16/2001	Inspect Date	RED TWELVE LEVERS FE Well No. 008Q	1/30/2001	6/12/2001	Inspect Date	2	6/12/2001	Inspect Date		RED TWELVE FEDERAL	2/12/2001
Z	Violation?		N _o	No	N _o	Violation?	FE	No	N _o	Violation?		No	Violation?			N _o
No Pumping Unit. NO FLOWLINE	Comments		OPERATOR SET BAKER MODEL R PACKER @2383' TOP PERFS. @2414' PESS. TEST START 590# STOP 560# 30 MIN. TEST	No Pumping Unit. NO FLOWLINE.	Hole in Ground (not capable of producing). Photo	Comments Comments		All OK. All Equipment and Location in Good Shape.B/T	Location needs attention. Equipment OK. Mtr Reading 2401			A-OK. All Equipment and Location in Good Shape.				No Motor on Pumping Unit.
30015251520000	API Number		30015250900000	30015250900000	30015250900000	API Number		30015250590000	30015250590000	API Number		30015250580000	API Number			30015248960000

API Number	? Comments	Violation?	Inspect Date	Status
				Well No. 006
30015249910000	START TEST 500# FOR 30 MIN END TEST 500# NO PRESS. LOSS	Z _o	11/16/2001	A
30015249910000	All OK. All Equipment and Location in Good Shape.	No	3/6/2001	Α
30015249910000	A-OK. All Equipment and Location in Good Shape.	No	10/16/2001	Α
API Number	Comments	Violation?	Inspect Date	Status
COMMISSION CONTRACTOR				Well No. 004
30015249890000	No top in Oil Tank. No net on open top water tank. Water tank contains hydrocarbons and water. No top in Oil tank.	Yes	5/16/2001	Ø
30015249890000	No Motor on Pumping Unit. No net on water tank. No top in oil tank	No	2/13/2001	S
API Number	Comments	Violation?	Inspect Date	Status
				Well No. 003
30015249660000	No Motor on Pumping Unit. PHOTO(DISK 1)B/T	N _o	6/11/2001	Α
API Number	Comments	Violation?	Inspect Date	Status
NAMA (Alley constitute properties and a sate of the sa				Well No. 002
30015249620000	No Motor on Pumping Unit. Photo	No	6/12/2001	>
API Number		Violation?	Inspect Date	Status
86. 4.5.4% (11.4.5.4.5.4%)				Weil No. 001
			/E STATE	RED TWELVE STATE
30015251520000	Hole in Ground (not capable of producing). Photo	No	10/16/2001	Α

Т	\dashv	7	\dashv	Т
6/17/2001	10/16/2001	1/31/2001	11/15/2001	11/16/2001
No	No	No	No	N _o
No Flowline. Photo	Location of well does not match lat/long. Photo	No Pumping Unit.	RIGGING UP TO RUN CSG. PRESS. TEST FOR T/A TALKED TO DEVIN GARNER SET PACKER @ 2500' TOP PERFS. 3006' PACKER NOT SET WITHIN 100' OF PERFS. CAN NOT RUN CSG. PRESS. OPERATOR WILL GET WITH O.C. D OFFICE	OPERATOR SAID PACKER SET @2873' PRESS. CSG TO 520# FOR 30MIN. PRESS. WAS AT 500# AT END OF TEST
30015250550000	30015250550000	30015250550000	30015250550000	30015250550000
	No No Flowline. Photo	No Location of well does not match lat/long. Photo No No Flowline. Photo	No No Pumping Unit. No Location of well does not match lat/long. Photo No No Flowline. Photo	No RIGGING UP TO RUN CSG. PRESS. TEST FOR T/A TALKED TO DEVIN GARNER SET PACKER @ 2500' TOP PERFS. 3006' PACKER NOT SET WITHIN 100' OF PERFS. CAN NOT RUN CSG. PRESS. OPERATOR WILL GET WITH O.C. D OFFICE No No Pumping Unit. No Location of well does not match lat/long. Photo No Flowline. Photo

STATE

Well No. 001

	***************************************	***************************************		**************************************
Status	Inspect Date	Violation?	Comments API Number	API Number
S	6/11/2001	Yes	No Pumping Unit. Separator improperly plumbed. Idle Well. Photo	30015028880000
S	2/13/2001	No	Separator plumbed to dump fluid on open ground.	30015028880000
Well No. 002	.~			
Status	Inspect Date	Violation?	Comments	API Number
Α	1/30/2001	No	. B/	30015028890000
>	6/15/2001	Yes	No Motor on Pumping Unit.	30015028890000

THEOS STATE

Well No. 001

EXPRENDENT CONTROL OF THE PROPERTY OF THE PROP			MINISTER STREET, STREE	**************************************
API Number	Comments	Violation?	Inspect Date	Status I

30015247320000	No Motor on Pumping Unit. NO RODS IN HOLE	Yes	1/30/2001	. ,
	@2453' WELL DID NOT LOAD O.C.D WELL FILE TOP PERFS. @2187' OPERATOR WILL RIG UP AND RESET PACKER			
30015247320000	OPERATOR SET LOC-SET PACKER @2415' TOP PERFS.	No	11/30/2001	7
30015247320000	PERFS. @2187' PACKER SET @ 2170' START TEST PRESS. 520# STOP PRESS. 520# 30 MIN. TEST	Š	12/3/2001	,