


ILLEGIBLE

EXHIBIT
6-A



Hobbs, NM
November 1, 1997
Photo Source:
USGS

Zoomed Image With Composite Interpretations

Vertical Tanks	Staining	Pits
New Tanks	Catwalk	Pits Removed
Tanks Removed	Levee	Probable Gathering Lines

30 0 30 60 Feet

N

AERO-DATA CORP.
ENVIRONMENTAL
REMOTE SENSING CONSULTING SERVICES
AERIAL PHOTO ANALYSIS
COMPOSITE PHOTO COMPOSITING