

EXHIBIT 3:

OFFSET INFORMATION FOR EXAMINER HEARING AT HOBBS JULY 25, 1956 CONCERNING APPLICATION FOR AN UNORTHODOX LOCATION 250' NORTH OF SOUTH LINE AND 250' WEST OF EAST LINE IN SECTION 31, TOWNSHIP 17 SOUTH, RANGE 30 EAST, LOCO HILLS PRESSURE MAINTENANCE POOL, EDDY COUNTY, NEW MEXICO.

Well	Location	Section	Township	Range	Date Well Completed	Date of Sand Oil Fracture Treatment	July 1956 Nomination B.O.P.D.	Date Well Plugged & Abandoned	Total Depth
(1) Brigham 1-A	SW $\frac{1}{4}$ SE $\frac{1}{4}$ SE $\frac{1}{4}$	31	17 S.	30 E.	4-4-40	6-20-55	8		2850
(2) Brigham 2-A	NW $\frac{1}{4}$ NE $\frac{1}{4}$ SE $\frac{1}{4}$	31	17 S.	30 E.	9-6-40		10		2883
(3) Yates 3-A	NW $\frac{1}{4}$ NW $\frac{1}{4}$ NE $\frac{1}{4}$	6	18 S.	30 E.	10-4-39	10-8-55	19		2710
(4) Yates 4-A	NW $\frac{1}{4}$ NE $\frac{1}{4}$ NE $\frac{1}{4}$	6	18 S.	30 E.	12-1-39		8		2848
(5) Yates 6-A	NW $\frac{1}{4}$ SW $\frac{1}{4}$ NE $\frac{1}{4}$	6	18 S.	30 E.	6-12-40	7-6-55	20		2855
(6) Yates 11-A	SE $\frac{1}{4}$ NW $\frac{1}{4}$ NE $\frac{1}{4}$	6	18 S.	30 E.	7-26-50	8-9-54	19		2841
(7) Coppedge 1	NW $\frac{1}{4}$ SW $\frac{1}{4}$ NW $\frac{1}{4}$	5	18 S.	30 E.	9-30-40			12-28-40	3445
(8) Coppedge 2	NW $\frac{1}{4}$ NW $\frac{1}{4}$ NW $\frac{1}{4}$	5	18 S.	30 E.	1-9-40			10-1-55*	2860
(9) Coppedge 3	1980' East of West Line & 330' South of North Line	5	18 S.	30 E.	7-10-41		2		2866
(10) Coppedge 4	NW $\frac{1}{4}$ NW $\frac{1}{4}$ NE $\frac{1}{4}$	5	18S.	30 E.	10-22-41			10-3-51	2885
(11) State 5-B	NW $\frac{1}{4}$ SW $\frac{1}{4}$ SW $\frac{1}{4}$	32	17 S.	30 E.	7-19-40			4-2-45	2867
(12) State 5-BX	SE $\frac{1}{4}$ SW $\frac{1}{4}$ SW $\frac{1}{4}$	32	17 S.	30 E.	4-7-45		38		2858
(13) State 3-B	NW $\frac{1}{4}$ NW $\frac{1}{4}$ SW $\frac{1}{4}$	32	17 S.	30 E.	10-14-40		22		2887
(14) State 1-B	SW $\frac{1}{4}$ NE $\frac{1}{4}$ SW $\frac{1}{4}$	32	17 S.	30 E.	3-15-40			3-28-40	2655

NOTE: *Temporarily Abandoned

BEFORE THE
CONSERVATION COMMISSION
SANTA FE, NEW MEXICO
JAN 28 1956
CASE 1101