

EI Paso Natural Gas Products Company
Case No. 1596
Exhibit No. 12
Date February 18, 1959

HORSESHOE GALLUP FIELD
SAN JUAN COUNTY, NEW MEXICO
BOTTOM HOLE PRESSURES SANDS "A" AND "B"

Operator	:	Location	:	Survey	:	Shut-In Time	:	BHP	:	Remarks	
Lease	:	Well No. :	1/4 1/4 Sec. - Twn-Rng	:	Date	:	Hours	:	* Sand "A" : ** Sand "B" : *** Sand "B"	:	
EI Paso Natural Gas Products Co.											
Horseshoe Canyon	1	NE SE	4-30-16		2-8-59		72		238	201	Natural Completion
Horseshoe Canyon	4	SE SW	3-30-16		11-1-57		48		243	209	Natural Completion Initial BHP Survey
Horseshoe Canyon	6	NW NW	10-30-16		1-28-59		43		194		Sandoll Fractured
Horseshoe Canyon	8	NE SW	4-30-16		1-29-59		192		180		Sandoll Fractured
Horseshoe Canyon	2-B	NE NW	4-30-16		9-24-57 10-4-57		49 48		276 221	243	Natural Completion Initial BHP Surveys

Gradient 0.335 psi/ft.

* Datum ≠ 4175'
** Datum ≠ 4075'
*** Datum ≠ 4175'

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100