








BEFORE EXAMINER NUTTER
OIL CONSERVATION COMMISSION
Carroll EXHIBIT NO. B
CASE NO. 1760

CASE NO. 1760
FLOW DIAGRAM OF TEST STATION NO. 1
ATLANTIC-NAVAJO "B" LEASE
HORSESHOE GALLUP FIELD
SAN JUAN COUNTY, NEW MEXICO
EXHIBIT "B"



BEFORE EXAMINATION
OIL CONSERVATION DEPARTMENT
Letell
CASE NO. 1760 EXHIBIT NO. C

CASE NO. 1760
DRAWING OF A DUMP TYPE METER
ATLANTIC-NAVAJO "B" LEASE
HORSESHOE GALLUP FIELD
SAN JUAN COUNTY, NEW MEXICO
EXHIBIT "C"

EXHIBIT D V

METERING ERRORS FOR DUMP TYPE METERS FROM ATLANTIC - NAVAJO LEASE

<u>DATE</u>	<u>STATION #1 ERROR %</u>	<u>STATION #2 ERROR %</u>	<u>STATION #3 ERROR %</u>
2-15-59	.18	.70	.18
3-21-59	.20	.20	.20
4-19-59	.32	.18	None
5-7-59	None	None	.13
6-19-59	None	None	None


BEFORE EXAMINER NUTTER

OIL CONSERVATION COMMISSION

Appl EXHIBIT NO. D

CASE NO. 1760


CASE NO. 1760



PROPOSED LACT INSTALLATION
ATLANTIC-NAVAJO "B" LEASE
EXHIBIT "E"
CASE NO. 1760

BEFORE EXAMINER NUTTER
OIL CONSERVATION COMMISSION
act EXHIBIT NO. E
CASE NO. 1760

OIL FROM
TEST STATION



1810/500
900

BEFORE EXAMINER NUTTER

OIL CONSERVATION COMMISSION

Apple EXHIBIT NO. F
CASE NO. 1760

DETAILS OF LACT UNIT
ATLANTIC-NAVAJO "B" LEASE

EXHIBIT "F"

CASE NO. 1760