


R 32 E



- Denotes USGLO Iron Pipe & Brass Cap: Found in Good Condition
- Denotes USGLO Iron Pipe & Brass Cap 1/4 Section Corner: Found in Good Condition

BEFORE EXAMINER UTZ
OIL CONSERVATION COMMISSION
AP EXHIBIT NO. 1
CASE NO. 2399

Plat Showing the Bearings and
Distances of Section Lines and
the Drilled Location of Cotton
Draw Unit Well No. 54 in Sec. 28
T-25-S R-32-E
Lea County New Mexico
Scale 1"=600' 10-2-61