

EPNG PRESSURE BUILD-UP TEST

TEST WELL DATA BALLARD PICTURED CLIFFS Pool

Date Jan. 7, 1963

TEST WELL: Operator: El Paso Natural Gas Company Well Name & No. Ballard #6

Location 1650 fr. N, 990 fr. W lines, E Sec. 14 T. 26 N., R. 9 W

TD: 2029 Casing: 5-1/2" @ 1994 Tubing: 1" @ 1996

Completed: August 15, 1954 First Delivery: October 1, 1954

Pay Zone: Open Hole Interval: 2000-2029 or Perforations:

Stimulation: Sand-oil frac.

SIPC: 656 SIPT: 657 DAYS SI: 11

I.P. Test: 2774 MCF, 3 hrs. Choke: MCF AOF thru tubing or casing

Current Deliverability: 416 MCF, Date Tested: 1962

WELLS ON SAME BASIC LEASE

<u>Name</u>	<u>Location</u>	<u>Deliverability</u>	<u>Date of Test</u>
Ballard #5	P- 14-26-9	177	1962
Ballard #3	H- 14-26-9	161	1962
Ballard #4	M-14-26-9	267	1962
Ballard #7	E- 15-26-9	292	1962
Ballard #8	H- 15-26-9	279	1962
Ballard #9	O- 15-26-9	224	1962
Ballard #10	L- 15-26-9	118	1962

SAN JUAN COUNTY, NEW MEXICO

BALLARD P C

TOWNSHIP 26-N RANGE 9-W