

EPNG PRESSURE BUILD-UP TEST

TEST WELL DATA BALLARD PICTURED CLIFFS Pool

Date Jan. 7, 1963

TEST WELL: Operator: El Paso Natural Gas Company Well Name & No. Wilson #A-1

Location 1296 fr. N, 1298 fr. W lines, F Sec. 32 T. 26 N., R. 8 W.

TD: 2128 Casing: 5-1/2" @ 2050 Tubing: 1" @ 2113

Completed: August 15, 1954 First Delivery: April 25, 1955

Pay Zone: Open Hole Interval: 2046-2128 or Perforations:

Stimulation: Sand-oil frac.

SIPC: 612 SIPT: 613 DAYS SI: 44

I. P. Test: 3490 MCF, 3 hrs. Choke: MCF AOF thru tubing or casing

Current Deliverability: 418 MCF, Date Tested: 1962

WELLS ON SAME BASIC LEASE

<u>Name</u>	<u>Location</u>	<u>Deliverability</u>	<u>Date of Test</u>
Wilson #A-2	K-32-26-8	417	1962

SAN JUAN COUNTY, NEW MEXICO

BALLARD P C

TOWNSHIP 26-N RANGE 8-W

