

LONE PINE DAKOTA "D" FIELD
MCKINLEY COUNTY, NEW MEXICO
"RECOVERY AS A FUNCTION OF
MAINTENANCE PRESSURE"

WEB

11-2-71 5.8

Slope = 3,498 BO/psi drop

5.1

Slope = 2,544 BO/psi drop

3.2

Examiner Utz

Case No. 460404665

EXHIBIT NO. 7

100

200

300

400

500

600

700

800

900

1000

Pressure @ which Maintenance Injection Begins, psi

Pressure