

SONLUMBERGER		BOREHOLE COMPENSATED SONIC LOG - GAMMA RAY	
COUNTY LEA FIELD or LOCATION JUSTIS WELL CORRIGAN # 1 COMPANY RHODES & RICHARDSON	COMPANY RHODES & RICHARDSON		
	WELL CORRIGAN # 1		
	FIELD JUSTIS		
	COUNTY LEA STATE NEW MEXICO		
	LOCATION 990' FROM S/L 990' FROM W/L		
Sec. 11 Twp. 25S Rge. 37E			Other Services: LL, MLL
Permanent Datum: GL, Elev. 3117			Elev.: K.B. 3130
Log Measured From KB 13 Ft. Above Perm. Datum			D.F. 3129
Drilling Measured From KB			G.L. 3117
Date	3-13-66		
Run No.	ONE		
Depth - Driller	5555		
Depth - Logger	5555		
Min. Log Interval	5556		
Top Log Interval	0		
Casing - Driller	8 5/8 @ 985	@	@
Casing - Logger	-		
Bit Size	7 7/8		
Type Fluid in Hole	SALT GEL.		
	STARCH		
Dens. Visc.	10.1 38		
pH Fluid Loss	6.5 10 ml	ml	ml
Source of Sample	CIRC.		
R ₁ @ Meas. Temp.	.059 @ 68 °F	@ °F	@ °F
R ₂ @ Meas. Temp.	.051 @ 64 °F	@ °F	@ °F
R ₃ @ Meas. Temp.	.087 @ 72 °F	@ °F	@ °F
Source: R ₁ R ₂	M M		
R ₄ @ RHT	.04 @ 106 °F	@ °F	@ °F
Time Since Circ.	4 HOURS		
Max. Rec. Temp.	106 °F	°F	°F
Equip. Location	4556 HOBBS		
Recorded By	TARBALL		
Witnessed By	MR. RHODES & MR. RICHARDSON		

Reproduced By

West Texas Electrical Log Service

Mesquite, TEXAS 79701

REFERENCE

W7676M



13

COMPLETION RECORD

SPUD DATE

COMP DATE

DST RECORD