


R 23 E

T 20 S

T 20 1/2 S

T 21 S




LEGEND

- Location
- ⊕ Plugged and Abandoned Well
- ☼ Canyon Gas Well
- ☼ Strawn Gas Well
- ⊛ Atoka Gas Well
- ⊛ Morrow Gas Well
- ⊕ Well Drilled to Morrow or Deeper

NP ← No Penetration

100' Structure Contours on Lower Canyon Marker

Fault



Inferred Fault



0 1 mile 2 miles

Scale

R 22 E

R 23 E

YATES PETROLEUM CORP.

STINKING DRAW UNIT

EDDY COUNTY, NEW MEXICO

EXHIBIT No. 3