





BEFORE THE
OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

Case No. ⁴⁷⁶³4764 Exhibit No. 1

Submitted by ⁴⁷⁶⁵Black River

Hearing Date 11/21/72



LEGEND

- ☼ Completed in Upper Morrow
- ✱ Completed in Lower Morrow
- ☼✱ Completed in Upper & Lower Morrow
- ✧ Dry Hole
- Well Location



BLACK RIVER CORPORATION

STRUCTURE MAP
 BOTTOM OF LWR. MORROW SAND
 C.I. = 100'

WASHINGTON RANCH (Morrow) FIELD
 EDDY COUNTY, NEW MEXICO

W. P. A. 11-20-72

SIPES, WILLIAMSON & RUNYAN, INC.
 Consulting Engineers Midland, Texas

EXHIBIT NO.

BEFORE THE
OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

Case No. 4763 Exhibit No. 2

Submitted by 4765 Black Limer

Hearing Date 11/21/72