



WIRELINE SERVICE
P. O. BOX 303
FARMINGTON, NEW MEXICO 87499

TELEPHONE NO: 505-327-2364
RADIO SERVICE: 505-325-5033
UNIT NO. 244 & 245

PAGE _____ OF _____

SUBSURFACE PRESSURE SURVEY

COMPANY SOUTHLAND ROYALTY CO. LEASE JOHNSON WELL NO. #1

FIELD _____ COUNTY RIO ARRIBA STATE NEW MEXICO

FORMATION MESA VERDE TEST DATE 01-22-84

ELEVATION _____	FEET	CASING _____	PSIG
SUBSEA DATUM _____	FEET	TUBING PRESSURE _____	PSIG
TOTAL DEPTH _____	FEET	OIL LEVEL _____	FEET
PERFORATIONS _____	FEET	WATER LEVEL _____	FEET
TUBING SIZE _____ TO _____	FEET	TEMPERATURE _____ F AT _____	FEET
CASING SIZE _____ TO _____	FEET	ATMOSPHERIC TEMPERATURE _____	F
PACKER _____	FEET	AMERADA ELEMENT NUMBER _____	
BOTTOM HOLE CHOKE _____	FEET	ELEMENT RANGE _____	
MAXIMUM SAFE TEST DEPTH _____	FEET	OPERATOR _____	UNIT NO. _____

WELL STATUS

<u>DEPTH</u> FEET	<u>PRESSURE</u> PSIG	<u>GRADIENT</u> PSI/FT.
0'	820	
2000'	873	0.030
4000'	926	0.030
5450'	963	0.030
5650'	968	0.030
5850'	973	0.030

EXHIBIT NO. 10
Mesaverde
B.H.P.