



WIRELINE SERVICE
P. O. BOX 303
FARMINGTON, NEW MEXICO 87499

TELEPHONE NO: 505-327-2364
RADIO SERVICE: 505-325-5033
UNIT NO. 244 & 245

PAGE _____ OF _____

SUBSURFACE PRESSURE SURVEY

COMPANY SOUTHLAND ROYALTY CO. LEASE JOHNSON WELL NO. #1

FIELD _____ COUNTY RIO ARriba STATE NEW MEXICO

FORMATION DAKOTA AND GALLUP TEST DATE 01-22-84

ELEVATION	_____	FEET	CASING	_____	PSIG
SUBSEA DATUM	_____	FEET	TUBING PRESSURE	_____	PSIG
TOTAL DEPTH	_____	FEET	OIL LEVEL	_____	FEET
PERFORATIONS	_____	FEET	WATER LEVEL	_____	FEET
TUBING SIZE	_____ TO _____	FEET	TEMPERATURE	_____ F AT _____	FEET
CASING SIZE	_____ TO _____	FEET	ATMOSPHERIC TEMPERATURE	_____	F
PACKER	_____	FEET	AMERADA ELEMENT NUMBER	_____	
BOTTOM HOLE CHOKE	_____	FEET	ELEMENT RANGE	_____	
MAXIMUM SAFE TEST DEPTH	_____	FEET	OPERATOR	_____	UNIT NO. _____

WELL STATUS

<u>DEPTH</u> FEET	<u>PRESSURE</u> PSIG	<u>GRADIENT</u> PSI/FT.
0'	834	
2000'	894	0.030
4000'	954	0.030
5250'	991	0.030
5450'	997	0.030
5650'	1004	0.035

EXHIBIT No. 11
Gallup/Dakota
B.H.P.