

**EXHIBIT NO. 1**  
**CASE NO. 9302**


This is a plat of the area around the north half of Section 1, T25N, R3W showing:

1. The stippled area is the non-standard unit which is the subject of this case.
2. The offset wells in the north half of Section 1 and the offset proration units to the north half of Section 1.
3. The wells shown in the southeast quarter, Hurt Federal #2 and #3, have not been drilled.

# OFFSET OPERATORS OR OWNERS

**R 3 W**

**R 2 W**



**BEFORE EXAMINER STOGNER  
OIL CONSERVATION DIVISION**

LITTLE      EXHIBIT NO.      1

CASE NO.      9302