


Imaging Log Indicates Secondary Porosity with Vugs as Large as 1' in Diameter

7845'-7855': Dolomite Interval with 0% Density-Neutron Porosity



← 360° of Hole image → 360° of Hole image

Imaging Log in Dolomite Indicating Vugular Porosity

BARBARA FED. #8

SE/4 Sec. 18

BEFORE EXAMINER
OIL CONSERVATION DIVISION

EXHIBIT NO. 12

CASE NO. 10221

Submitted by Conoco Inc.

Hearing Date 2-7-91

EXHIBIT 12