

**DAILY FIELD TRIP REPORT  
DISTRICT I**

SPEC	L	A	O	U	C	I	R	T	E	R	
TI											
ON											

NAME Durward R Smith DATE 2-13-85 MILES 178  
DEPARTURE 7 AM RETURN 4 PM CAR NO. 6243

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature Durward R Smith

T	U	I	3		1 well - Texaco, Inc. - N Vac Abo W Ut. #25-34-17-34 - SW Buckeye area - pkr test - pkr set going in hole - had to bring pkr out of hole - did not test.
R	U	S	5		1 well - Fannie Lee Mitchell - Caudill C-32 SWD in 32-15-36 - E Lovington area - have not been able to release slips to pull tbg.
					<div style="border: 1px solid black; padding: 5px; display: inline-block;">BEFORE EXAMINED ON DATA SHEET OR CONSIDERATION OF ACTION</div> OCD 2 Job No. 9042

Mileage

UIC 178

RFA

Other

Per Diem

UIC 6.00

RFA

Other

Hours

UIC 8

RFA

Other

**TYPE INSPECTION  
PERFORMED**

- Housekeeping
- Plugging
- Plugging Cleanup
- Well Test
- Repair/Workover
- Waterflow
- Hishap or Spill
- Water Contamination
- Other

**INSPECTION  
CLASSIFICATION**

- Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)
- Inspections relating to Reclamation Fund Activity
- Other - Inspections not related to Injection or The Reclamation Fund
- E - Indicate some form of enforcement action taken in the field (show immediately below the letter U, R or O)

**NATURE OF SPECIFIC WELL  
OR FACILITY INSPECTED**

- Drilling
- Production
- Injection
- Combined prod. inj. operations
- SWD
- Underground Storage
- General Operation
- Facility or location
- Meeting
- Other

DAILY FIELD TRIP REPORT  
DISTRICT I

S P E C T I O N	L A S S I F I C A T I O N	A C U R T E R H O U R S	NAME <u>Durward R Smith</u>	DATE <u>2-14-85</u>	MILES <u>122</u>
			DEPARTURE <u>7 AM</u>	RETURN <u>4 PM</u>	CAR NO. <u>6243</u>
In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.					
Signature <u>DURWARD R SMITH</u>					

T	U	I	2	1 well - Texaco - N Vac Abo W Ut. #25-34-17-34 - to witness pkr test - pkr is set @ 8607" & tested o.k. - located SW Buckeye area.
P	U	I	2	1 well - Phillips Pet. Co. - Leamex #8-23-17-33 - NW Buckeye area - set retainer @ 3608' & spot 300 sx cmt under retainer - spot 50 sx plug @ 2800' & 1 @ 1500".
R	U	S	1	1 well - Fannie Lee Mitchell - Caudill C-32-32-15-36 - E Lovington area - fishing for tbg out of hole.
P	O	P	3	1 well - El Ran, Inc. - Billy Bob #1-7-18-39 - NE Hobbs area - spot 40 sx cmt @ 2100' across 4 1/2" & 2 3/8" stub.

Mileage	Per Diem	Hours
UIC <u>100</u>	4.00	UIC <u>5</u>
RFA		RFA
Other <u>22</u>	2.00	Other <u>3</u>

TYPE INSPECTION PERFORMED	INSPECTION CLASSIFICATION	NATURE OF SPECIFIC WELL OR FACILITY INSPECTED
H = Housekeeping	U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)	D = Drilling
P = Plugging	R = Inspections relating to Reclamation Fund Activity	P = Production
C = Plugging/Cleanup	O = Other - Inspections not related to injection or the Reclamation Fund	I = Injection
T = Well Test	E = Indicated some form of enforcement action taken in the field (show immediately below the letter U, R or O)	C = Combined prod. Inj. operations
R = Repair/Workover		SWD = SWD
F = Waterflow		U = Underground Storage
M = Hishop or Spill		G = General Operation
W = Water Contamination		F = Facility or location
O = Other		H = Meeting
		O = Other

## DISTRICT I

NAME Durward R Smith DATE 2-15-85 MILES 131  
 DEPARTURE 7 AM RETURN 4 PM CAR NO. 6243

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature (Signature)

O	U	S	2	1 well - Cabot Corp. - Reed #1-35-13-37 - McDonald area - to check inj press - csg psi = 0 & tbg psi = 1930#.
R	U	S	3	1 well - Fannie Lee Mitchell - Caudill C-32-32-15-37 - E Lovington area - fishing tbg out of hole - depth less than 200'.
P	O	P	3	1 well - El Ran, Inc. - Billy Bob #1-7-18-39 - NE Hobbs area - lacked 13 stands of tbg in getting down to tag cmt plug on 4 1/2" csg stub - spot plug at 440' - wait 4 hrs & tag - did not find plug - spot another plug at 440' & circ cmt to surf - set marker.

Mileage	Per Diem	Hours
UIC <u>100</u>	UIC <u>4.00</u>	UIC <u>5</u>
RFA	RFA	RFA
Other <u>31</u>	Other <u>2.00</u>	Other <u>3</u>

TYPE INSPECTION PERFORMED	INSPECTION CLASSIFICATION	NATURE OF SPECIFIC WELL OR FACILITY INSPECTED
H = Housekeeping	U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)	D = Drilling
P = Plugging	R = Inspections relating to Reclamation Fund Activity	P = Production
C = Plugging Cleanup	O = Other - Inspections not related to injection or the Reclamation Fund	I = Injection
T = Well Test	E = Indicate some form of enforcement action taken in the field (show immediately below the letter U, R or O)	C = Combined prod. inj. operations
R = Repair/Workover		SWD
F = Waterflow		Underground Storage
B = Bishop or Spill		G = General Operation
W = Water Contamination		F = Facility or location
O = Other		H = Hunting
		O = Other

DAILY FIELD TRIP REPORT  
DISTRICT I

H	S	P	C	I	L	O	U
S	P	T	S	I	S	A	R
P	E	I	F	R	T	R	T
T	I	T	I	T	E	E	R
I	C	C	C	C	H	H	O
O	N	N	N	N	O	O	U
S	N	N	N	N	R	R	R

NAME Durward R Smith DATE 2-18-85 MILES 200  
 DEPARTURE 7 AM RETURN 4 PM CAR NO. 6243

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature Durward R Smith

H O P 6      45 wells - Housekeeping - E Lovington area & W Hobbs area - Pyro Energy, Michaelson Producing Corp., Adobe Oil, Belco Dev., Yates Pet., Fred Pool, David Fasken, & Phillips Pet. - all wells are o.k.

R U S 2      1 well - Fannie Lee Mitchell - Caudill C-32-32-15-37 SWD - E Lovington area - had rigged down & moved before repairs were completed.

<u>Mileage</u>	<u>Per Diem</u>	<u>Hours</u>
UIC <u>40</u>	UIC <u>2.00</u>	UIC <u>2</u>
RFA _____	RFA _____	RFA _____
Other <u>160</u>	Other <u>4.00</u>	Other <u>6</u>

TYPE INSPECTION PERFORMED	INSPECTION CLASSIFICATION	NATURE OF SPECIFIC WELL OR FACILITY INSPECTED
---------------------------	---------------------------	---

H = Housekeeping  
 P = Plugging  
 C = Plugging/Cleanup  
 T = Well Test  
 R = Repair/Workover  
 F = Waterflow  
 M = Hishap or Spill  
 W = Water Contamination  
 O = Other

U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry Injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)  
 R = Inspections relating to Reclamation Fund Activity  
 O = Other - Inspections not related to injection or the Reclamation Fund  
 E = Indicated some form of enforcement action taken in the field (show immediately below the letter U, R or O)

D = Drilling  
 P = Production  
 I = Injection  
 C = Combined prod. inj. operations  
 S = SWD  
 U = Underground Storage  
 G = General Operation  
 F = Facility or location  
 H = Meeting  
 O = Other

NEW MEXICO OIL CONSERVATION COMMISSION  
DAILY FIELD TRIP REPORT  
DISTRICT I

J	C	H	Q	
I	A	O	U	R
S	C	A	L	T
E	I	R	S	R
T	F	E	I	R
I	P	H	O	R
N	S	O	U	R
S	E	A	L	T
P	C	R	S	R
E	I	E	I	R
T	F	H	O	R
I	P	O	U	R
N	S	A	L	T
S	E	R	S	R
O	C	I	I	R
N	T	H	O	R
T	I	O	U	R
O	N	N	S	R

NAME Durward R Smith DATE 2-22-85 MILES 150  
DEPARTURE 7 AM RETURN 4 PM 3 PM CAR NO. 6243

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature Durward R Smith

H	U	S	3	2 wells - Verde Grande - Aztec SWD in 18-16-37 - SE Lovington area - to check cleanup operations - cleanup o.k.
H	O	P	2	Araho - SWD in 1-17-30 - SE Lovington area - checking cleanup & housekeeping procedures - Oil & water on ground - notified operator by phone.
R	U	S	3	20 wells - Housekeeping - SE Lovington area - Yates, Getty, ARCO, Amerind, Texas Crude - Sohio - Harvey E Yates, W A Moncrief, & Tipperary Oil & Gas Co. - all wells are in good shape.
				1 well - Fannie Lee Mitchell - Caudill G-32-32-15-37 - E Lovington area - to witness workover operations - still fishing for tbg.

Mileage	Per Diem	Hours
UIC <u>75</u>	UIC <u>4.00</u>	UIC <u>5.6</u>
RFA _____	RFA _____	RFA _____
Other <u>75</u>	Other <u>2.00</u>	Other <u>3.3</u>

TYPE INSPECTION PERFORMED	INSPECTION CLASSIFICATION	NATURE OF SPECIFIC WELL OR FACILITY INSPECTED
---------------------------	---------------------------	---

H = Housekeeping  
P = Plugging  
C = Plugging/Cleanup  
T = Well Test  
R = Repair/Workover  
F = Waterflow  
S = Hishop or Spill  
W = Water Contamination  
O = Other

U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)  
R = Inspections relating to Reclamation Fund Activity  
O = Other - Inspections not related to injection or the Reclamation Fund  
E = Indicated good form of enforcement action taken in the field

D = Drilling  
P = Production  
I = Injection  
C = Combined prod. inj. operations  
S = SWD  
U = Underground Storage  
G = General Operation  
F = Facility or location  
H = Hunting  
O = Other

DAILY FIELD TRIP REPORT  
DISTRICT I

H	S	P	E	C	L	O	U	A	R	T	E	R
S	I	F	I	A	I	S	I	C	I	S	I	S
E	C	P	C	C	P	S	I	N	P	O	N	T
CT	Y	AT										
IO	N	AT										

NAME Durward R Smith DATE 2-25-85 MILES 152  
DEPARTURE 7 AM RETURN 4 PM CAR NO. 6243

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature Durward R Smith

R	U	S	2	1 well - Fannie Lee Mitchell - Caudill G-32-32-15-37 - E Lovington area - working over tbg @ 270'.
H	U	S	1	1 well - Araho - SWD in 1-17-35 - S Lovington area - there has been no cleanup work done.
R	O	P	2	1 well - Phillips Pet. - Lea St. #18-30-34-17 - unable to pump into well - survey was no good.
R	U	I	1	1 well - Phillips Pet. - VATRG 68H in 34-17-34 - drilling on iron @ 8848'.
H	U	C	2	30 wells - Housekeeping - W Lovington & E Buckeye area - Chaveroo, Pioneer Prod., BTA Oil Producers, & Texaco - all wells are in good shape except for the following:  Chaveroo Operating - LSA Lease - had oil standing around well head & stuffing box was leaking - also, had leaks in oil tank @ battery - left note for pumper to get cleaned up & to repair tank.

Mileage	Per Diem	Hours
UIC <u>100</u>	UIC <u>4.00</u>	UIC <u>6</u>
RFA <u></u>	RFA <u></u>	RFA <u></u>
Other <u>52</u>	Other <u>2.00</u>	Other <u>2</u>

TYPE INSPECTION PERFORMED	INSPECTION CLASSIFICATION	NATURE OF SPECIFIC WELL OR FACILITY INSPECTED
E = Housekeeping	U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells; water flows or pressure tests, surface injection equipment, plugging, etc.)	D = Drilling
P = Plugging	R = Inspections relating to Reclamation Fund Activity	P = Production
C = Plugging/Cleanup	O = Other - Inspections not related to Injection or the Reclamation Fund	I = Injection
T = Well Test	E = Indication form of enforcement action taken in the field (show immediately below the letter U, R or O)	C = Combined prod. inj. operations
R = Repair/Workover		S = SWD
F = Waterflow		U = Underground Storage
H = Hishop or Spill		G = General Operation
W = Water Contamination		F = Facility or location
O = Other		H = Hunting
		O = Other

DAILY FIELD TRIP REPORT  
DISTRICT I

S	L	O	U			
S	A	C	I	R	A	R
P	S	I	S	T	T	E
E	F	I	L	E	R	R
C	T	I	T	H	O	O
I	C	Y				
O	A	T				
N	T	I				

NAME Durward R Smith DATE 2-26-85 MILES 157  
DEPARTURE 7 AM RETURN 5 PM CAR NO. 6243

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature Durward R Smith

R U S 2      1 well - Fannie Lee Mitchell - Caudill G-32-32-15-36 - E Lovington area - ✓ working @ 400' over tbg.

R O P 2      1 well - Phillips Pet. - Lea St. #18-30-34-17 - circ cmt between 6 5/8 & 8 5/8 to surf, ✓

T U I 5      1 well - Mobil Oil Co. - N Vac Abo #173 in 14-17-34 - N Buckeye area - ✓ test pkr - test was o.k.

Mileage  
UIC 100  
RFA \_\_\_\_\_  
Other 37

Per Diem  
UIC 4.00  
RFA \_\_\_\_\_  
Other 2.00

Hours  
UIC 7  
RFA \_\_\_\_\_  
Other 2

TYPE INSPECTION  
PERFORMED

INSPECTION  
CLASSIFICATION

NATURE OF SPECIFIC WELL  
OR FACILITY INSPECTED

H = Housekeeping  
P = Plugging  
C = Plugging Cleanup  
T = Well Test  
R = Repair/Workover  
F = Waterflow  
S = Hishop or Spill  
W = Water Contamination  
O = Other

U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)  
R = Inspections relating to Reclamation Fund Activity  
O = Other - Inspections not related to Injection or the Reclamation Fund  
E = Indicated some form of enforcement action taken in the field (show immediately below the letter U, R or O)

D = Drilling  
P = Production  
I = Injection  
C = Combined prod. inj. operations  
G = SWD  
U = Underground Storage  
G = General Operation  
F = Facility or location  
H = Meeting  
O = Other

**DAILY FIELD TRIP REPORT  
DISTRICT I**

L	A	O	U	R	R	DATE	2-27-85	MILES	109
S	C	I	S	T	E	DEPARTURE	7 AM	RETURN	4 PM
P	S	I	S	T	R			CAR NO.	6243
C	I	F	T	I	R				
T	I	T	C	I	O				
I	C	Y							
O									
N									

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature Durward R Smith

T	U	I	3	1 well - Mobil Oil Co. - Bridges St. #132-26-17-34 - pkr test - test o.k. ✓
H	U	S	1	1 well - Araho - SWD in 1-17-35 - has been no cleanup & pit is full. ✓
R	U	S	4	1 well - Fannie Lee Mitchell - Caudill G-32-32-17-35 - workover operations around 500". ✓

<u>Mileage</u>	<u>Per Diem</u>	<u>Hours</u>
UIC 109	UIC 6.00	UIC 8
RFA	RFA	RFA
Other	Other	Other

**TYPE INSPECTION  
PERFORMED**

H = Housekeeping  
 P = Plugging  
 C = Plugging Cleanup  
 T = Well Test  
 R = Repair/Workover  
 F = Waterflow  
 M = Mishap or Spill  
 W = Water Contamination  
 O = Other

**INSPECTION  
CLASSIFICATION**

U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)  
 R = Inspections relating to Reclamation Fund Activity  
 O = Other - Inspections not related to Injection or the Reclamation Fund  
 E = Indicated some form of enforcement action taken in the field (show immediately below the letter U, R or O)

D = Drilling  
 P = Production  
 I = Injection  
 C = Combined prod. inj. operations  
 S = SWD  
 U = Underground Storage  
 G = General Operation  
 F = Facility or location  
 H = Meeting  
 O = Other

## DAILY FIELD TRIP RETURN

## DISTRICT I

O  
U  
R  
T  
E  
RJ  
A  
R  
T  
E  
RH  
O  
U  
R  
S

NAME Durward R Smith DATE 2-28-85 MILES 170  
 DEPARTURE 7 AM RETURN 4 PM CAR NO. 6243

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature Durward R Smith

- |      |   |
|------|---|
| \$ 4 | 1 well - Fannie Lee Mitchell - Caudill G-32-32-15-37 - E Lovington area - fishing for tbg @ 501'.   |
| \$ 2 | 1 well - Phillips Pet. Co. - Lea St. #18-30-34-17 - drilling out cmt retainer after squeeze @ 910'.   |
| \$ 2 | 35 wells - Housekeeping - NW Hobbs area - Getty, Mesa Pet., ARCO, Consolidated, & David Fasken - all wells are o.k. - Buckeye area - Phillips Pet., Cities Services, & Mobil Oil - all wells are o.k. |

Mileage	Per Diem	Hours
UIC <u>70</u>	UIC <u>3.00</u>	UIC <u>4</u>
RFA	RFA	RFA
Other <u>100</u>	Other <u>3.00</u>	Other <u>4</u>

INSPECTION CLASSIFICATION		NATURE OF SPECIFIC WELL OR FACILITY INSPECTED
Setup	U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry Injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)	D = Drilling P = Production I = Injection C = Combined prod. inj operations S = SWD U = Underground Storage
over	R = Inspections relating to Reclamation Fund Activity	G = General Operation F = Facility or location
Illination	O = Other - Inspections not related to Injection or The Reclamation Fund	H = Hunting O = Other
	E = Indicator code form of enforcement action taken in the field (show immediately below the letter U, R or O)	

## NEW MEXICO OIL CONSERVATION COMMISSION

## DAILY FIELD TRIP REPORT

## DISTRICT I

I	C	F	H	Q
S	A	A	O	U
P	C	C	A	A
E	S	I	R	R
T	S	E	Q	U
I	I	R	A	R
C	T	R	T	S
A	Y	Y	T	S
T				
I				
O				
N				

NAME Durward R Smith DATE 3-1-85 MILES 162  
 DEPARTURE 7 AM RETURN 4 PM CAR NO. 6243

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature Durward R Smith

R	O	P	2	1 well - Phillips Pet. - Lea St. #18-30-34-17 - W Buckeye area - press csg to 700# & csg did not hole - spot plug @ 310'.
R	U	I	3	1 well - Texaco - VSGSAU #33-1-18-34 - sq holes in csg @ 285'-380' - shut down.
R	U	S	3	1 well - Fannie Lee Mitchell - Caudill G-32-32-15-36 - E Lovington area - fishing @ 565'.

Mileage	Per Diem	Hours
UIC <u>100</u>	UIC <u>4.00</u>	UIC <u>6</u>
RFA <u></u>	RFA <u></u>	RFA <u></u>
Other <u>62</u>	Other <u>2.00</u>	Other <u>2</u>

TYPE INSPECTION  
PERFORMEDINSPECTION  
CLASSIFICATIONNATURE OF SPECIFIC WELL  
OR FACILITY INSPECTED

H = Housekeeping  
P = Plugging  
C = Plugging Cleanup  
T = Well Test  
R = Repair/Workover  
F = Waterflow  
M = Mishap or Spill  
W = Water Contamination  
O = Other

U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)  
R = Inspections relating to Reclamation Fund Activity  
O = Other - Inspections not related to injection or the Reclamation Fund

E = Indicate some form of enforcement action taken in the field (see immediately below the letter U, R or O)

D = Drilling  
P = Production  
I = Injection  
C = Combined prod. inj operations  
B = SWD  
U = Underground Storage  
G = General Operation  
F = Facility or location  
H = Hunting  
O = Other

DAILY FIELD TRIP REPORT  
DISTRICT I

C I T Y  C A T I O N	U Q A R T E R  H O U R S	NAME <u>Durward R Smith</u>	DATE <u>3-4-85</u>	MILES <u>161</u>
		DEPARTURE <u>7 AM</u>	RETURN <u>4 PM</u>	CAR NO. <u>6243</u>
R	O	P	1	1 well - Phillips Pet. - Lea St. #18-30-34-17 - W Buckeye area - drill out cmt to press up on csg - csg did not hold.
R	U	I	2	1 well - Texaco - VGBSAU #33-1-18-34 - drilling out cmt - still have waterflow.
R	U	S	3	1 well - Fannie Lee Mitchell - Caudill G-32-32-15-36 - E Lovington area - washing over tbg @ 686'.
P	O	P	2	1 well - Pennzoil - Rock Island #2-3-17-34 - NW Buckeye area - setting CIBP @ 10,090'.

<u>Mileage</u>	<u>Per Diem</u>	<u>Hours</u>
<u>UIC</u> <u>100</u>	<u>UIC</u> <u>4.00</u>	<u>UIC</u> <u>5</u>
<u>RFA</u>	<u>RFA</u>	<u>RFA</u>
<u>Other</u> <u>61</u>	<u>Other</u> <u>2.00</u>	<u>Other</u> <u>3</u>

TYPE INSPECTION PERFORMED	INSPECTION CLASSIFICATION	NATURE OF SPECIFIC WELL OR FACILITY INSPECTED
H - Housekeeping	U - Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)	D - Drilling
P - Flushing	R - Inspections relating to Reclamation Fund Activity	P - Production
C - Plugging/Cleanup	O - Other - Inspections not related to injection or the Reclamation Fund	I - Injection
T - Well Test	E - Indicated form of enforcement action taken in the field (show immediately below the letter U, R or O)	C - Combined prod. inj operations
R - Repair/Workover		S - SWD
F - Waterflow		U - Underground Storage
M - Mishap or Spill		G - General Operation
W - Water Contamination		F - Facility or location
O - Other		H - Hunting
		O - Other

DAILY FIELD TRIP REPORT  
DISTRICT I

ACTION	TYPE	QUARTER HOURS	NAME	DATE	MILES
			DEPARTURE	RETURN	CAR NO.
			Durward R Smith	3-5-85	130
			7 AM	4 PM	6243

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature Durward R Smith

P	O	P	2	1 well - Pennzoil - Rock Island #2-3-17-34 - Buckeye area - to witness plugging operations - NW Buckeye area - spot 20 sx cmt @ 7963'-8063' - 20 sx cmt @ 5987'-6087'.
R	U	S	2	1 well - Fannie Lee Mitchell - Caudill G-32-32-15-35 - E Lovington - workover operations - wash over & pull 62' of 3 1/2" tbg - top of fish now @ 847'.
R	U	I	1	1 well - Phillips Pet - V A Tr 5 #2-0-26-17-35 - E Buckeye area - to check workover operations.
R	O	P	1	1 well - Phillips Pet - Lea St 18-30-34-17 - W Buckeye area - to check workover operations.
R	U	I	1	1 well - Texaco - VGBSAU #33-1-18-34 - S Buckeye area - to witness workover operations - have drill out & still have waterflow.
T	U	I	1	1 well - Texaco - NVAWU #18-27-17-34 - SW Buckeye - to witness pkr test - test o.k.

Mileage	Per Diem	Hours
UIC _____ 80	UIC _____ 4.00	UIC _____ 5
RFA _____	RFA _____	RFA _____
Other _____ 50	Other _____ 2.00	Other _____ 3

TYPE INSPECTION PERFORMED	INSPECTION CLASSIFICATION	NATURE OF SPECIFIC WELL OR FACILITY INSPECTED
H = Housekeeping	U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)	D = Drilling
P = Plugging	R = Inspections relating to Reclamation Fund Activity	P = Production
C = Plugging Cleanup	O = Other - Inspections not related to injection or the Reclamation Fund	I = Injection
T = Well Test	E = Indicate some form of enforcement action taken in the field (show immediately below the letter U, R or O)	C = Combined prod. inj. operations
R = Repair/Workover		S = SWD
F = Waterflow		U = Underground Storage
M = Misuse or Spill		G = General Operation
W = Water Contamination		F = Facility or location
O = Other		H = Meeting
		O = Other

**DAILY FIELD TRIP REPORT  
DISTRICT I**

I T Y	Q U A R T E R	H O U R S	<b>NAME</b> <u>Durward R Smith</u>	<b>DATE</b> <u>3-6-85</u>	<b>MILES</b> <u>190</u>
			<b>DEPARTURE</b> <u>7 AM</u>	<b>RETURN</b> <u>4 PM</u>	<b>CAR NO.</b> <u>6243</u>

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature Durward R Smith

P	O	P	4	2 wells - to witness plugging operations on the following:  Pennzoil - Rock Island #2-3-17-34 - cut 5 1/2" csg @ 4100' - Buckeye area Elk Oil Co - Etcheverry St Com #1-5-15-34 - Lovington - pull 8 5/8" csg
R	U	S	2	1 well - Fannie Lee Mitchell - Caudell G-32-15-36 - E Lovington - washing over 3 1/2" tbg.
R	G	I	2	1 well - Texaco - VGBSAU #33-1-18-34 - S Buckeye - workover operations - S Buckeye - sq waterflow @ 380'.

<u>Mileage</u>	<u>Per Diem</u>	<u>Hours</u>
<u>UIC</u> <u>100</u>	<u>UIC</u> <u>3.00</u>	<u>UIC</u> <u>4</u>
<u>RFA</u> _____	<u>RFA</u> _____	<u>RFA</u> _____
<u>Other</u> <u>90</u>	<u>Other</u> <u>3.00</u>	<u>Other</u> <u>4</u>

**TYPE INSPECTION  
PERFORMED**

H = Housekeeping  
 P = Plugging  
 C = Plugging Cleanup  
 T = Well Test  
 R = Repair/Workover  
 F = Waterflow  
 M = Mishap or Spill  
 W = Water Contamination  
 O = Other

**INSPECTION  
CLASSIFICATION**

U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)  
 R = Inspections relating to Reclamation Fund Activity  
 O = Other - Inspections not related to injection or the Reclamation Fund  
 E = Indicate some form of enforcement action taken in the field (show immediately below the letter U, R or O)

**NATURE OF SPECIFIC WELL  
OR FACILITY INSPECTED**

D = Drilling  
 P = Production  
 I = Injection  
 C = Combined prod. inj. operations  
 SWD  
 U = Underground Storage  
 G = General Operation  
 F = Facility or location  
 H = Hunting  
 O = Other

DAILY FIELD TRIP REPORT  
DISTRICT I

NAME Durward R Smith DATE 3-7-85 MILES 77  
DEPARTURE 7 AM RETURN 4 PM CAR NO. 6243

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

**Signature**

R U S 4 1 well - Lovington area - Fannie Lee Mitchell - workover operations -  
Caudill G-32-32-15-36 - fishing for tbg - top of sih now @  
1006'.

P O P 4 1 well - NW Lovington area - Elk Oil Co. - plugging operations -  
Etchenverry St Com. #1-5-15-34 - could not get tbg back in-  
side of 8 5/8" csg @ 830' - pumped 200' of cmt.

Mileage	Per Diem	Hours
UIC 30	UIC 3.00	UIC 4
RFA	RFA	RFA
Other 47	Other 3.00	Other 4

**TYPE INSPECTION  
PERFORMED**

**INSPECTION  
CLASSIFICATION**

**NATURE OF SPECIFIC RE-  
OR FACILITY INSPECTED**

**H** = Housekeeping  
**P** = Plugging  
**C** = Plugging/Cleanup  
**T** = Well Test  
**R** = Repair/Workover  
**F** = Waterflow  
**M** = Mishap or Spill  
**W** = Water Contaminat  
**S** = Safety

- U** = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (E&D, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)
- R** = Inspections relating to Reclamation Fund Activity
- O** = Other - Inspections not related to injection or The Reclamation Fund.

- D = Drilling
- P = Production
- I = Injection
- C = Combined prod. in operations
- S = SWD
- U = Underground Storage
- G = General Operation
- F = Facility or location
- H = Heating
- O = Other

NEW MEXICO OIL CONSERVATION COMMISSION  
DAILY FIELD TRIP REPORT  
DISTRICT I

P E R  H O U R S	NAME <u>Eddie W Seay</u>	DATE <u>3-8-85</u>	MILES <u>126</u>
	DEPARTURE <u>7 AM</u>	RETURN <u>4 PM</u>	CAR NO. <u>7360</u>

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature Eddie W Seay

U	S	2	1 well - S Lovington - Araho #2-2-17-36 - rigging up to change pkr & clean out.	
R	U	S	4	1 well - Lovington area - Fannie Lee Mitchell - Caudill G-32-32-15-36 - run fishing tool - retrieved 63' of fish - run wash pipe & wash over 3 1/2" csg.
M	U	S	2	1 other - Eunice area - to check pipeline break - Mobil Prod. in 33-21-37 - break in SWD line - call Mr. Truman Auld to repair.

Mileage	Per Diem	Hours
UIC <u>126</u>	UIC <u>6.00</u>	UIC <u>8</u>
RFA _____	RFA _____	RFA _____
Other _____	Other _____	Other _____

TYPE INSPECTION PERFORMED	INSPECTION CLASSIFICATION	NATURE OF SPECIFIC WELL OR FACILITY INSPECTED
H = Housekeeping	U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)	D = Drilling
P = Plugging	R = Inspections relating to Reclamation Fund Activity	P = Production
C = Plugging/Cleanup	O = Other - Inspections not related to Injection or The Reclamation Fund	I = Injection
T = Well Test	E = Indicate some form of enforcement action taken in the	C = Combined prod. inj. operations
R = Repair/Workover		S = SWD
F = Waterflow		U = Underground Storage
S = Hishop or Spill		G = General Operation
W = Water Contamination		F = Facility or location
O = Other		H = Hunting
		O = Other

DAILY FIELD TRIP REPORT  
DISTRICT I

J  
R  
SQ  
U  
A  
R  
T  
E  
RT  
Y  
  
I  
T  
I  
O  
N  
  
H  
O  
U  
R  
S

NAME Durward R Smith DATE 3-11-85 MILES 132  
 DEPARTURE 7 AM RETURN 4 PM CAR NO. 6243

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature Durward R Smith

R	U	S	3	1 well - Fannie Lee Mitchell - Lovington area - workover operations - Caudell G-32-32-15-36 - milling on tbg @ 1170'.
P	O	P	4	2 wells - NW Loving area - witness plugging operations - Elk Oil Co - Marie St Com #1-5-15-34 - could not get csg cutter below 4993' - spot 100' cmt inside 5 1/2" csg @ 8000' & one @ 6000'.  Robert M Edsel - Edsel St #1-30-14-37 - CIBP set @ 10,750' - circ hole w/salt gel.
H	O	P	1	1 well - E Buckeye area - Monument Energy - ISA lease - there has been no cleanup action taken - oil is still on the ground at the well & around the north stock tank - contacted co rep to get cleaned up.

Mileage	Per Diem	Hours
UIC <u>32</u>	UIC <u>2.00</u>	UIC <u>3</u>
RFA <u></u>	RFA <u></u>	RFA <u></u>
.Other <u>100</u>	Other <u>4.00</u>	Other <u>5</u>

TYPE INSPECTION  
PERFORMED

INSPECTION  
CLASSIFICATION

NATURE OF SPECIFIC WELL  
OR FACILITY INSPECTED

- H = Housekeeping
- P = Plugging
- C = Plugging Cleanup
- T = Well Test
- R = Repair/Workover
- F = Waterflow
- M = Mishap or Spill
- W = Water Contamination
- O = Other

- U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)
- R = Inspections relating to Reclamation Fund Activity
- O = Other - Inspections not related to injection or the Reclamation Fund
- E = Indication form of enforcement action taken in the field (show immediately below the letter U, R or O)

- D = Drilling
- P = Production
- I = Injection
- C = Combined prod. In operations
- SWD
- Underground Store
- G = General Operation
- F = Facility or location
- M = Meeting
- O = Other

DISTRICT 1

NAME	Durward R Smith	DATE	3-12-85	MILES	120
DEPARTURE	7 AM	RETURN	4 PM	CAR NO.	6243

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

**Signature**

P O P 4      2 well - Lovington & Hilburn areas - plugging operations on the following:  
.  
Elk Oil Co. - Marie St Com #1-5-15-34 - cut 5 1/2" csg @ 4564' -  
& laying down pipe.  
Robert M Edsel - Edsel State #1-30-14-37 - spot 136' of cmt  
on CIBP @ 10,750' - tag top @ 10614'.  
R U S 4      1 well - to witness workover - Fannie Lee Mitchell - Caudell G-32-32-15-36  
- lay down 90' of 3 1/2" tbg - top of fish now @ 1200'.

Mileage	Per Diem	Hours
UIC 40	UIC 3.00	UIC 4
RFA	RFA	RFA
Other 80	Other 3.00	Other 4

**TYPE INSPECTION  
PERFORMED**

**INSPECTION  
CLASSIFICATION**

**NATURE OF SPECIFIC WORK FACILITY INSPECTED**

**H = Housekeeping**  
**P = Plugging**  
**C = Plugging/Cleanup**  
**T = Well Test**  
**R = Repair/Workover**  
**F = Waterflow**  
**M = Mishap or Spill**  
**W = Water Contamination**  
**O = Other**

**U** = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (E&D, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)

**R** = Inspections relating to Reclamation Fund Activity

**O** = Other - Inspections not related to Injection or The Reclamation Fund

**E** = Indicates some form of enforcement action taken in the field (show immediately below the letter U, R or O)

**D** = Drilling  
**P** = Production  
**I** = Injection  
**C** = Combined prod. &  
 operations  
**S** = SWD  
**U** = Underground Stor  
**G** = General Operatio  
**F** = Facility or loca  
**H** = Hunting  
**O** = Other

**DAILY FIELD TRIP REPORT**  
**DISTRICT I**

J R S	U A T	NAME <u>Durward R Smith</u>	DATE <u>3-14-85</u>	MILES <u>144</u>
T Y	E R	DEPARTURE <u>7 AM</u>	RETURN <u>4 PM</u>	CAR NO. <u>6243</u>
T I O N	H O U R S	In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.		

Signature Durward R Smith

H (E)	U S	1	10 vent boots - SE Maljamar area - Housekeeping - Agua SWD pipeline - Corbin SWD - everything o.k. except for 3 boots running over in 33-12-33 - notified Agua.
P O	P	3	2 wells - NW Lovington area - plugging operations on the following:  Elk Oil Co. - Marie St Com #1-5-15-34 - cut 9 5/8" csg @ 450'. Kersey St 5-C in 32-17-32 - scrapes in hole on tbg.
R U	S	4	2 wells - Lovington area - workover operations on following:  Fannie Lee Mitchell - Caudell G-32-32-15-36 - top of fish @ 1470'. Verde Grande - Aztec St #1-18-16-37 - hole in csg around 5300' - could not get pkr to hole - P.O.H.

<u>Mileage</u>	<u>Per Diem</u>	<u>Hours</u>
UIC <u>90</u>	UIC <u>4.00</u>	UIC <u>5</u>
RFA	RFA	RFA
.Other <u>54</u>	Other <u>2.00</u>	Other <u>3</u>

TYPE INSPECTION PERFORMED	INSPECTION CLASSIFICATION	NATURE OF SPECIFIC WELL OR FACILITY INSPECTED
H = Housekeeping P = Plugging C = Plugging Cleanup T = Well Test R = Repair/Workover F = Waterflow M = Mishap or Spill W = Water Contamination O = Other	U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.) R = Inspections relating to Reclamation Fund Activity .O = Other - Inspections not related to injection or the Reclamation Fund E = Indicate some form of enforcement action taken in the field (show immediately below the letter U, R or O)	D = Drilling P = Production I = Injection C = Combined prod. inj. operations B = SWD U = Underground Storage G = General Operation F = Facility or location H = Meeting O = Other

## DISTRICT I

J N C A T I O N	S T Y	R T E R H O U R S	NAME	DATE	MILES	**
			DEPARTURE	RETURN	4 PM	CAR NO.
			Jackie R Griffin	3-14-85		

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature Jackie R Griffin

H U S 1 10 vent boots - SE Maljamar area - Housekeeping - Agua SWD pipeline - Corbin SWD - everything o.k. except for 3 boots running over in 33-12-33 - notified Agua.

P O P 3 2 wells - NW Lovington area - plugging operations on the following:  
 Elk Oil Co. - Marie St Com #1-5-15-34 - cut 9 5/8" csg @ 450'.  
 Kersey St 5-C in 32-17-32 - scrapes in hole on tbg.

R U S 4 2 wells - Lovington area - workover operations on following:

Fannie Lee Mitchell - Caudell G-32-32-15-36 - top of fish @ 1470'.  
 Verde Grande - Aztec St #1-18-16-37 - hole in csg around 5300' - could not get pkr to hole - P.O.H.

Mileage	Per Diem	Hours
UIC **	UIC 4.00	UIC 5
RFA	RFA	RFA
Other **	Other 2.00	Other 3

TYPE INSPECTION  
PERFORMED

H = Housekeeping  
 P = Plugging  
 C = Plugging Cleanup  
 T = Well Test  
 R = Repair/Workover  
 F = Waterflow  
 M = Hishop or Spill  
 W = Water Contamination  
 O = Other

INSPECTION  
CLASSIFICATION

U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)  
 R = Inspections relating to Reclamation Fund Activity  
 O = Other - Inspections not related to injection or the Reclamation Fund  
 E = Indicate some form of enforcement action taken in the field (show immediately below the letter U, R or O)

NATURE OF SPECIFIC  
OR FACILITY INSPEC

D = Drilling  
 P = Production  
 I = Injection  
 C = Combined prod. operations  
 B = SWD  
 U = Underground Stc  
 G = General Operat  
 F = Facility or loc  
 H = Hunting  
 O = Other

NEW MEXICO OIL CONSERVATION COMMISSION  
DAILY FIELD TRIP REPORT  
DISTRICT I

NAME Durward R Smith DATE 3-15-85 MILES 211  
DEPARTURE 7 AM RETURN 4 PM CAR NO. 6243

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature Suzanne R Smith

R U S 4 2 wells - Lovington area - Fannie Lee Mitchell - Caudell G-32-32-15-36 - workover operations - top of fish @ 1590'.

Lovington area - Verde Grande - Aztec St. #1-18-16-37 - run scraper to clean csg wall.

P O P 4 3 wells - to witness plugging operations on the following:

S Maljamar area - Kersey Oil - Hover #5-32-17-32

NW Lovington area - Elk Oil - Marie St Com #1-5-15-34 - spot  
135 sx plug @ 500'. to cover 9 5/8" csg stub & surf shoe -  
tag @ 230' - spot 10' surf plug.

Hilburn area - Robert M Edsel - Edsel St 30-14-37 - spot  
310' plug @ 6740'-7050' - spot plug @ 4888' & tag @  
4695'.

<u>Mileage</u>	<u>Per Diem</u>	<u>Hours</u>
UIC      50	UIC      3.00	UIC      4
RFA	RFA	RFA
Other     161	Other     3.00	Other     4

**TYPE INSPECTION  
PERFORMED**

INSPECTION  
CLASSIFICATION

**NATURE OF SPECIFIC WELL  
OR FACILITY INSPECTED**

**H = Housekeeping**  
**P = Plugging**  
**C = Plugging/Cleanup**  
**T = Well Test**  
**R = Repair/Workover**  
**F = Waterflow**  
**M = Mishap or Spill**  
**W = Water Contamination**

**U** = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well). (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)

**R** = Inspections relating to Reclamation Fund Activity

**D** = Drilling  
**P** = Production  
**I** = Injection  
**C** = Combined prod. inj.  
 operations  
**S** = SWD  
**U** = Underground Storage  
**G** = General Operation  
**F** = Facility or location  
**H** = Heating  
**O** = Other

DAILY FIELD TRIP REPORT  
DISTRICT I

		NAME <u>Durward R Smith</u>	DATE <u>3-19-85</u>	MILES <u>**</u>
		DEPARTURE <u>7 AM</u>	RETURN <u>4 PM</u>	CAR NO. <u>**</u>

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature Durward R Smith

R I O N	T Y	S U A R T E R H O U R S				
			2	WELLS	LEADS	
R	U	S	5	2 wells - Lovington area - workover operations on the following:		
				Fannie Lee Mitchell - Caudell G-32-32-15-36 - washing over 3 1/2" tbg - top of fish now @ 1670'.		
T	U	I	3	1 well - Buckeye area - to witness pkr test on Texaco, Inc. - NVAbco Unit #21-28-17-34 - test was o.k.		

Mileage	Per Diem	Hours
UIC <u>**</u>	UIC <u>6.00</u>	UIC <u>8</u>
RFA _____	RFA _____	RFA _____
Other _____	Other _____	Other _____

TYPE INSPECTION PERFORMED	INSPECTION CLASSIFICATION	NATURE OF SPECIFIC WELL OR FACILITY INSPECTED
------------------------------	------------------------------	--

H = Housekeeping  
P = Plugging  
C = Plugging Cleanup  
T = Well Test  
R = Repair/Workover  
F = Waterflow  
M = Hishop or Spill  
W = Water Contamination  
O = Other

U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)  
R = Inspections relating to Reclamation Fund Activity  
O = Other - Inspections not related to injection or the Reclamation Fund  
E = Indication some form of enforcement action taken in the field (show immediately below the letter U, R or O)

D = Drilling  
P = Production  
I = Injection  
C = Combined prod. int. operations  
S = SWD  
U = Underground Storage  
G = General Operation  
F = Facility or location  
M = Meeting  
O = Other

## DISTRICT 1

TYPE ATION	QUARTER TER	HOURS	NAME <u>Durward R Smith</u>	DATE <u>3-20-85</u>	MILES <u>163</u>
			DEPARTURE <u>7 AM</u>	RETURN <u>4 PM</u>	CAR NO. <u>6243</u>
H O G (E)	6		In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.		
R U S	2		<p>37 wells - N Hobbs Area - Housekeeping - Discovery Operating, S E Cone, Jr., Baber Well Services, Polaris, &amp; Maralo - all wells o.k.</p> <p>Gladiola area - Housekeeping - Wanico, Elk Oil, Amoco, Texaco, Gulf, Amerada, Cities Services, Skelton, Ingram Oil, &amp; Kimbark - all wells &amp; t/b's are all o.k. except for a storage facility two miles W of Gladiola in 21-12-37 for J M Petroleum Co. - left note to cover oil on ground &amp; empty pump under loading header.</p> <p>2 wells - Lovington area - workover operations on the following:</p> <p>Fannie Lee Mitchell - Caudell G-32-32-15-36 - top of fish now @ 1930'.</p> <p>Verde Grande - Axtec St. #1-18-16-37 - drilled out cmt &amp; R.I.H. w/tbg.</p>		
			<u>Mileage</u> UIC <u>40</u> RFA _____ Other <u>123</u>	<u>Per Diem</u> UIC <u>2.00</u> RFA _____ Other <u>4.00</u>	<u>Hours</u> UIC <u>2</u> RFA _____ Other <u>6</u>

TYPE INSPECTION  
PERFORMED

H = Housekeeping  
P = Plugging  
C = Plugging/Cleanup  
T = Well Test  
R = Repair/Workover  
F = Waterflow  
S = Mishap or Spill  
W = Water Contamination  
O = Other

INSPECTION  
CLASSIFICATION

U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)

R = Inspections relating to Reclamation Fund Activity

O = Other - Inspections not related to injection or the Reclamation Fund

E = Indicate some form of enforcement action taken in the field (show immediately below the letter U, R or O)

NATURE OF SPECIFIC  
OR FACILITY INSPECTED

D = Drilling  
P = Production  
I = Injection  
C = Combined prod. / operations  
S = SWD  
U = Underground Sto  
G = General Operati  
F = Facility or loc  
H = Meeting  
O = Other

DAILY FIELD TRIP REPORT  
DISTRICT I

QUARTER HOURS	NAME <u>Durward R Smith</u>	DATE <u>3-21-85</u>	MILES <u>144</u>
DEPARTURE <u>7 AM</u>	RETURN <u>4 PM</u>	CAR NO. <u>6243</u>	

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited, and any action taken.

Signature Durward R Smith

R	U	S	2	2 wells - Lovington area - workover operations on the following:  Fannie Lee Mitchell - Caudell G-32-32-15-36 - top of fish still @ 1930;.  Verde Grande - Aztec #1-18-16-37 - drilling out cmt after squeezing.
H	O	C	6	50 wells - SW Buckeye area - Housekeeping on the following:  Sohio, Phillips, ARCO, Murphy H Baxter, Cities Services, Mobil Oil, Petroleum Corp. of Texas, Manzano, Yates Petroleum, Hillard Oil & Gas, C W Trainer, Beach Expl., & Union Oil of CA - all wells are in good shape.

Mileage	Per Diem	Hours
UIC <u>44</u>	UIC <u>2.00</u>	UIC <u>2</u>
RFA <u></u>	RFA <u></u>	RFA <u></u>
Other <u>100</u>	Other <u>4.00</u>	Other <u>6</u>

TYPE INSPECTION  
PERFORMED

H = Housekeeping  
P = Plugging  
C = Plugging Cleanup  
T = Well Test  
R = Repair/Workover  
F = Waterflow  
M = Hushup or Spill  
W = Water Contamination  
O = Other

INSPECTION  
CLASSIFICATION

U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)  
R = Inspections relating to Reclamation Fund Activity  
O = Other - Inspections not related to injection or the Reclamation Fund  
E = Indicates some form of enforcement action taken in the field (show immediately below the letter U, R or O)

NATURE OF SPECIFIC W  
OR FACILITY INSPECTED

D = Drilling  
P = Production  
I = Injection  
C = Combined prod. & operations  
S = SWD  
U = Underground Stor  
G = General Operatio  
F = Facility or loc  
H = Meeting  
O = Other

**DAILY FIELD TRIP REPORT**  
**DISTRICT I**

J R S	I E T	NAME <u>Durward R Smith</u>	DATE <u>3-22-85</u>	MILES <u>124</u>
A T I O N	H O U R S	DEPARTURE <u>7 AM</u>	RETURN <u>4 PM</u>	CAR NO. <u>6243</u>

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Signature Durward R Smith

R U S 4      2 wells - Lovington area - workover operations on the following:

Fannie Lee Mitchell - Caudell G-32-32-15-36 - top of fish now @ 2030'.

Verde Grande - Aztec #1-18-16-37 - drilling out cmt after squeezing.

H O G 4      40 wells - Lovington area - Housekeeping on the following:

Getty Oil, Harvey E Yates, Penzoil, Blanks Energy, Union Oil of CA, Yates Pet., Amerada, & Amoco - all wells are in good shape except for Blanks Energy in 18-16-37 - had no sign on battery or well - left note to correce this.

Mileage

UIC 62

RFA

Other 62

Per Diem

UIC 3.00

RFA

Other 3.00

Hours

UIC 4

RFA

Other 4

TYPE INSPECTION  
PERFORMED

H = Housekeeping  
P = Plugging  
C = Plugging Cleanup  
T = Well Test  
R = Repair/Workover  
F = Waterflow  
M = Mishap or Spill  
W = Water Contamination  
O = Other

INSPECTION  
CLASSIFICATION

U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)  
R = Inspections relating to Reclamation Fund activity  
O = Other - Inspections not related to injection or The Reclamation Fund  
E = Indicate form of enforcement action taken in the field (show immediately below the letter U, R or O)

NATURE OF SPECIFIC WELL  
OR FACILITY INSPECTED

D = Drilling  
P = Production  
I = Injection  
C = Combined prod. inj. operations  
S = SWD  
U = Underground Storage  
G = General Operation  
F = Facility or location  
H = Hunting  
O = Other