


BEFORE EXAMINER CATANACH
OIL CONSERVATION DIVISION

W/M EXHIBIT NO. 34
1996

Chaco 5, Fracture Dimensions

CASE NO. _____



CHACO #5 PETCOM 10

3 Jun 1998 @ 14:46

DEPTH (FT)

GRN	200	PAFLAG65	0	5	2	ILD	2000	2	RHOB	3	0.5	PHIDC	0	0	VCL	dec	1
SP	20	PAFLAG65							RHOB	3	1	SWT	DEC	-1	0	COALFLAG	1
PAFLAG75	0														0	VCL	
PAFLAG75	0														0	VCL	1
															0	COALFLAG	

