## Received 04/09/2020 NMOCD District 2

Submit One Copy To Appropriate District  State of New Mexico	Form C-103
Office District I  Energy, Minerals and Natural Resources	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-015-26591 5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	0. 0 0 0 0 0 0
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	MEDANO VA STATE
1. Type of Well: Oil Well Gas Well Other	8. Well Number #3
2. Name of Operator EOG RESOURCES, INC	9. OGRID Number 7377
3. Address of Operator	10. Pool name or Wildcat
PO BOX 2267 MIDLAND, TEXAS 79702	LOS MEDANOS; DELAWARE
4. Well Location	·
Unit Letter <u>F</u> : <u>2310</u> feet from the NORTH_line and <u>1650</u> feet from the <u>WEST_line</u>	
Section 16 Township 23S Range 31E NMPM County EDDY	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3349' GL	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL W	
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE	DRILLING OPNS. ☐ P AND A ☐
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEN	IENT JOB
OTHER:	is ready for OCD increation after DOA
OTHER:	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
☐ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment. 3rd Denial - No Change - trash pile in same place	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.  Buried power lines not removed  All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
<ul> <li>✓ All other environmental concerns have been addressed as per OCD rules.</li> </ul>	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE KAY MANDE TITLE: REGULATORY	SPECIALIST DATE 04/07/2020
TYPE OR PRINT NAME: KAY MADDOX E-MAIL: <u>kay maddox@eogresour</u>	rces.com PHONE: 432-686-3658
For State Use Only	<u></u>
DENIED	4/04/0000
APPROVED BY:	DATEgc4/24/2020
Conditions of Approval (if any):	