

Division I
1631 N. Rosach Dr., Hobbs, NM 88240
Phone: (505) 392-4101 Fax: (505) 392-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name BXP Operating, LLC	API Number 30-015-04566
Property Name North Benson Queen Unit	Well No. 37

Surface Location								
UL - Lot B	Section 34	Township 18S	Range 30E	Feet from 660	NS Line N	Feet from 1980	E/W Line E	County EDDY

Well Status								
YES	TA'D WELL ☒ NO	YES	SHUT-IN ☒ NO	☒ INJECTOR	SWD	OIL	GAS	DATE 6-18-2020

OBSERVED DATA

	(A) Surface	(B) Intern (1)	(C) Intern (2)	(D) Prod Comp	(E) Tubing
Pressure	0			0	530
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 WTR ✓ GAS — Type of fluid is listed for verification if applies
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION
Printed name: M.Y. Merchant	Entered into RBDMS
Title: Production supervisor	Re-test
E-mail Address: mymerch@penrocoil.com	Accepted for recorded NMOCD
Date: 6-18-2020	DS 8-11-2020
Phone: 575-492-1236	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM