

OCD - REC'D 7/24/2020

Bladder
1021 N. Penrod Dr., Hobbs, NM 88240
Phone: (505) 393-4101 Fax: (505) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name BXP Operating, LLC	API Number 30-015-10193
Property Name North Benson Queen Unit	Well No. 23

Surface Location									
UL - Lot P	Section 28	Township 18S	Range 30E		Foot from 330	NS Line S	Foot from 330	EAV Line E	County EDDY

Well Status									
YES	TA'D WELL ☒ NO	YES	SHUT-IN ☒ NO	☒ INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 6-18-2020

OBSERVED DATA

	(A) Surface	(B) Intern (1)	(C) Intern (2)	(D) Prod Cmg	(E) Tubing
Pressure	0			60	260
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 WTR GAS Type of fluid is listed for Wellhead if applies
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Burges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION
Printed name: M.Y. Merchant	Entered into RBDMS
Title: Production Supervisor	Re-test
E-mail Address: mymerch@penrocoil.com	Accepted for recordd NMOCD
Date: 6-18-2020	DS 8-11-2020
Phone: 575-492-1236	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM