


# State Of New Mexico

## Energy, Minerals and Natural Resources Department

**Michelle Lujan Grisham**  
Governor  
**Sarah Cottrell Propst**  
Cabinet Secretary  
**Todd E. Leahy, JD, PhD**  
Deputy Cabinet Secretary

**Adrienne Sandoval**  
Division Director



### **"Response Required - Deadline Enclosed"**

*Field Inspection Program  
"Preserving the Integrity of Our Environment"*

15-Oct-20

**BXP Operating, LLC**  
P.O. Box 7227  
Dallas, TX 75209

### **LETTER OF VIOLATION - Field Inspection**

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

### ***INSPECTION DETAIL SECTION***

[30-015-32202] USA 9 FEDERAL COM #002Q

OGRID: 329487

A-09-20S-28E 660 FNL 660 FEL

Inspection Date	Type Inspection	Inspector	Corrective Action Due By	Inspection No.
9/24/2020	Routine Inspection	[GC] Gilbert Cordero	1/15/2021	iGC2026848494

#### **Violations:**

Rule	Violation
19.15.16.8 Sign on Wells	Inaccurate Information

**Comment:**  
API NUMBER AND WELL NUMBER NOT CORRECT

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

*Staff Manager*  
Artesia OCD District Office

**Note:** Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

**From:** [Cordero, Gilbert, EMNRD](#)  
**To:** ["rbrown@bxpltd.com"; "bguerrero@bxpltd.com"](#)  
**Subject:** LOV  
**Date:** Thursday, October 15, 2020 9:59:00 AM  
**Attachments:** [3001532202 BXP LOV 10 15 2020.pdf](#)  
[3001527682 BXP LOV 10 15 2020.pdf](#)

---

Good morning,

Attached please find a Letter of Violation (LOV) for the following wells.

30-015-32202 – USA 9 Federal Com 002Q - API number and well number are incorrect on well sign

30-015-27682 – Remington Federal 002 - Well sign is not legible

Thank you,

Gilbert Cordero  
Staff Manager  
NMOCD NM South  
Cell 575.626.0830