NMOCD Rec'd: 9/23/2020

Submit One Copy To Appropriate District Office	State of New Mexico			Form C-103		
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources			Revised November 3, 2011 WELL API NO.		
<u>District II</u> 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION			30-015-26980		
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			5. Indicate Type of Lease STATE FEE		
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505			6. State Oil & Gas Lease No.		
87505				K-6385		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Lease Name of Dee 36 SE State	r Unit Agre	ement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				8. Well Number		
1. Type of Well: Oil Well Gas Well Other				6		
2. Name of Operator				9. OGRID Numb	er	
EOG Y Resources, Inc. 3. Address of Operator				7377 10. Pool name or Wildcat		
104 South Fourth Street, Artesia, NM 88210				N. Seven Rivers; Glorieta – Yeso, North		
4. Well Location						
Unit Letter I: 1830 feet from the South line and 890 feet from the East line						
Section 36 Township 19S Range 24E NMPM Eddy County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)						
3589' GR						
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐						CASING .
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB						ш
OTHER: Location is ready for OCD inspection after P&A						
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.						
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.						
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the						
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR						
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.						
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Buried power lines removed. Buried flow line beside road has been properly abandoned.						
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.						
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with						
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. Trash on location & in pasture removed.						
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have						
to be removed.) Risers besides road to location are active (Attached Lucid email).						
 ✓ All other environmental concerns have been addressed as per OCD rules. ✓ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- 						
retrieved flow lines and pipelines. No, active pipeline(s) within EOG Resources gas system.						
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well						
location, except for utility's distribution infrastructure. Flow line markers removed (9/22/2020).						
When all work has been completed, return this form to the appropriate District office to schedule an inspection.						
SIGNATURE (JA	Ju.	_ TITLE:	Environmental Supe	ervisor	DATE 9/	23/2020
TYPE OR PRINT NAME: Robert A	sher	E-MAIL:	Robert Asher@eo	gresources.com	PHONE: 5'	75-748-4217
For State Use Only						
APPROVED BY:	Olmo	TITLE	Staff Man	aaer	DATE	10/23/2020
Conditions of Approval (if any):			3240// 1 10010		_DATE	. 0, 20, 2020

From: Jason Fuentes < JFuentes@lucid-energy.com>

Sent: Friday, February 7, 2020 12:51 PM

To: Bob Asher <Bob_Asher@eogresources.com> **Cc:** Frankie Soto <FSoto@lucid-energy.com>

Subject: Dee State 36

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Lucid is requesting the risers at the Dee 36SE State #5 & #6 remain in place due to the fact that it is attached to an active pipeline that remains in gas gathering service. Lucid will install a pipe around the riser for security. If the system volumes allow for removal in the future Lucid will cut/cap the riser below grade.

Thank you,

Jason S. Fuentes Sr. Director of Pipeline Operations



201 S. 4th Street Artesia, NM Office 575.810.6136 | Cell 575.365.8939 jfuentes@lucid-energy.com | www.lucid-energy.com