NMOCD Rec'd: 10/12/2020

DATE gc 11/4/2020

	INIMO	CD Rec a: 10/12/2020
Submit One Copy To Appropriate District Office	State of New Mexico	Form C-103
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources	Revised November 3, 2011 WELL API NO.
District II	OIL CONSERVATION DIVISION	30-015-26448
811 S. First St., Artesia, NM 88210 District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	STATE FEE S
1220 S. St. Francis Dr., Santa Fe, NM		6. State Oil & Gas Lease No.
87505 SUNDRY NOTI	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		CAVINESS
PROPOSALS.)	<u> </u>	8. Well Number
<i>7</i> = =	Gas Well Other INJECTION	1
2. Name of Operator CHEVRON USA Inc.		9. OGRID Number 4323
3. Address of Operator		10. Pool name or Wildcat
6301 Deauville Blvd., Midland, TX	. 79706	Lovington, Brushy Canyon, East
4. Well Location:		
Unit Letter_P_:_760_feet from the <u>SOUTH</u> line and 630_feet from the <u>EAST</u> line Section <u>15</u> Township <u>23-S</u> Range <u>28-E</u> NMPM County <u>EDDY</u>		
Section 15 Township	23-S Range 28-E NMPM County EDDY 11. Elevation (Show whether DR, RKB, RT, GR, etc.	
	3,827' GL	,
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF IN	TENTION TO: SUE	SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON ☐ REMEDIAL WOF	· · · · · · · · · · · · · · · · · · ·
TEMPORARILY ABANDON	_	RILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEMEN	II JOB
OTHER:		ready for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.		
 ⊠ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. ∑ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
☐ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.		
to be removed.) Location sign not removed		
 ✓ All other environmental concerns have been addressed as per OCD rules. ✓ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- 		
retrieved flow lines and pipelines.		
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well		
location, except for utility's distribut	ion infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.		
SIGNATURE Katherine Papageorge TITLE Decommissioning Project Manager DATE 10.12.20		
TYPE OR PRINT NAMEKatheri For State Use Only	ne Papageorge_E-MAIL: _Katherine.Papageorge@cl	hevron.com PHONE:832-854-5291

DENIED

APPROVED BY:_