

District II - Artesia
811 S. 1st Street, Artesia, NM 88210
Phone: (575) 748-1283 - Fax: (575) 748-9720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name OXY		API Number 30-015-29330	
Property Name Lost Tank 33 Federal #1		Well No. # 2	

2. Surface Location

UL - Lot M	Section 33	Township 21S	Range 31E	Feet from 330	N/S Line N	Feet From 510	E/W Line E	County Eddy
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	-----------------------

Well Status

TA'D Well YES NO	SHUT-IN YES NO	INJECTOR INJ SWD	PRODUCER OIL GAS	DATE 10-7-20
---------------------	--------------------------	----------------------------	---------------------	------------------------

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure	0	0		0	1250
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR _____
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

A - Puff Water
B - Puff Gas
D - Puff Water

Accepted for record test not witnessed
NMOCD DS 12-16-2020

Signature: _____		OIL CONSERVATION DIVISION	
Printed name: Reggie House		Entered _____	
Title: Production Tech II		Re-test _____	
E-mail Address: reggie-house@oxy.com			
Date: 10-7-20	Phone: 575-942-0363		
Signature: Reggie House	Witness: _____		