

STATE OF NEW MEXICO  
OFFICE OF STATE GEOLOGIST  
SANTA FE, NEW MEXICO

INSPECTION REPORT

October 15, 1951

Ray Oil Company and T. A. Kirk - Hoover No. 1 NWSE  
Section 30-11N-28E., Quay County, New Mexico

This location was inspected this day and found that they had drilled to 560' and had set 13 3/8 casing with 25 sacks of cement and was at this time bottomed in redbeds which I believe is called Santa Rosa ss. in this area.

They are drilling 15" hole at this time and had encountered water from 502' to 510'. The day tour driller was Mr. Ralston.

This well was actually spudded before receipt of the bond. However, the bond was received in the Santa Fe office on the date of inspection. This well is in the Hoover Ranch and is located approximately five miles east of Montoya. Surface conditions indicate possible anticline.

ELVIS A. UTZ,  
Gas Engineer

10-31-51  
lr