

OIL CONSERVATION COMMISSION

P. O. BOX 871

SANTA FE, NEW MEXICO

INSPECTION REPORT

June 13, 1952

NEWTON R. ROBERTS

Re: McCune No. 1
NWNE - Sec. 22-11N-13E
San Miguel County

C
O
P
Y
Today I visited the above captioned location, which is best reached by turning north from Highway 66 at the cattleguard one mile east of Palma service station. This station is about 8 miles east of Clines Corners and the well is 13.5 miles north of the highway. The road from the highway is a graded dirt road and there are two gates to open before reaching the location. The left fork of this road is taken after passing the first ranch house, thence this road leads directly to the well.

At the time of my inspection the drilling equipment was completely rigged up and the rat hole was being drilled preparatory to spudding in the well. A Mr. Don "Red" Conder is the tool pusher representing E. G. Goldsworthy of Cortez, Colorado, the drilling contractor. Mr. Fred L. Baker is the manager representing the operator, Newton R. Roberts of Denver, Colorado.

The rig is a jack-knife rotary capable of the proposed 2100' total depth.

I left an ample supply of sample bags with Mr. Baker for the Commission's cut of cuttings' samples.

E.A.C.

EUGENE A. CHAVEZ,
Geological Scout