

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-51424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR
Virgle Landreth

3. ADDRESS OF OPERATOR
5534 Fredricksburg Rd. Apt. 132 San Antonio Texas 78229

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
1980' FNL & 1980' FEL

14. PERMIT NO.
5774 GL

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5. LEASE DESIGNATION AND SERIAL NO.
N. M. 13386

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Panhandle "A"

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec 28 T4S R6E

12. COUNTY OR PARISH
Socorro

13. STATE
N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NATURE OF INTERVENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other) Surface casing	<input checked="" type="checkbox"/>
(Other)	<input type="checkbox"/>		
REPAIRING WELL	<input type="checkbox"/>		
ALTERING CASING	<input type="checkbox"/>		
ABANDONMENT*	<input type="checkbox"/>		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED WORK. Give location and pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Spudded 12 1/4" hole at 2:15 A. M. 4-25-73. Drilled to 360'.
Halliburton cemented 8 5/8" Csg. at 348' with 125 sks. Halliburton
light & 50 sks. regular. Total of 175 sks. with 2% Ca Cl & 1/4#
Flocele per sk. Cement circulated. Cement job complete at 5:00 P.M.
4-29-73. Nippled up and started drilling 5:00 P.M. 4-29-73.

RECEIVED
MAY - 4 1973
U. S. GEOLOGICAL SURVEY
ALBANY, NEW YORK

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]*

(This space for Federal or State office use)

Agent for Virgle Landreth

TITLE

DATE **5-3-73**

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side