NERGY AND MINERALS DEPARTMENT	
OIL CONSERVATION DIVISION	
P. O. BOX 2088	. Form C-103
SANTA FE SANTA FE, NEW MEXICO 87501	Revised 10-1-1
U.S.C.Z.	
LAND OFFICE	Sa. Indicate Type of Lease
OPERATOR .	
UPCHATOA .	5, State Oil & Gas Lease No.
	•
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR PROPASALS TO DAILL OR TO DEEPEN OF PLUG BACK TO'A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
	7. Unit Agreement Name
OIL I GAS WELL OTHER-	
ime of Operato:	Benz, Benz
Lyle Benz, Curtis Benz	8. Farm or Lease Hame
dress of Chertotor	Benz
	9. Well No.
P.O. 198 Estancia, New Mexico 87016	
cation o: #ell	
D Too	10. Field and Pool, or Wildran
UNIT LETTER D 730 PRET PROM THE West LINE AND 875 PRET PI	wildcat
-	
THE NOTTH LINE, BECTION 18 TOWASHIP 50 RANGE 9E	
	••• *//////////////////////////////////
()))))))))))))))))))))))))))))))))))))	
ground level elev. 6095	12. County
	Torrance
Check Appropriate Box To Indicate Nature of Notice, Report or (Other Date
NOTICE OF INTENTION TO:	
SUBSEQUE	NT REPORT OF:
DAM REMEDIAL WORK	
PLOG AND ABANDON REMEDIAL WORK	ALTERING CASING
OPARILY ABANDON COMMENCE DRILLING OPHS.	
	PLUG AND ABANDONMENT
CASING TEST AND CEMENT JOSTER	
Scribe Proposed of Completed Oceanity of Classical States	
escribe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includi wk) SEE RULE 1103.	ng estimated date of starting any proposed
	•
1. 6-24-84 Set casing string	
2. 6-25-84 Cemented casing string	
2.6-25-84Cemented casing string3.6-30-84Pressure tested casing string	
2. 6-25-84 Cemented casing string 3. 6-30-84 Pressure tested casing string 1. Casing is 4 ¹ / ₂ , 9.51b.e 8rd thread short caller	
2. 6-25-84 Cemented casing string 3. 6-30-84 Pressure tested casing string 1. Casing is 4 ¹ / ₂ , 9.51b.e 8rd thread short caller	with a float collar
2. 6-25-84 Cemented casing string 3. 6-30-84 Pressure tested casing string 1. Casing is 4 ¹ / ₂ , 9.51b.e 8rd thread short caller	with a float collar a 796 ft., $6\frac{1}{2}$ inch
 2. 6-25-84 Cemented casing string 3. 6-30-84 Pressure tested casing string 1. Casing is 4¹/₂, 9.51b., 8rd thread, short collars, range 2, winstalled on bottom, It is set to a depth of 793 ft. in diam. hole. 	a 796 ft., 6 [±] inch
 2. 6-25-84 Cemented casing string 3. 6-30-84 Pressure tested casing string 1. Casing is 4¹/₂, 9.51b., 8rd thread, short collars, range 2, with a line to bottom, It is set to a depth of 793 ft. in diam. hole. 2. Cementing was done by Denton Cementing of Antonia No. 	a 796 ft., $6\frac{1}{2}$ inch
 2. 6-25-84 Cemented casing string 3. 6-30-84 Pressure tested casing string 1. Casing is 4¹/₂, 9.51b., 8rd thread, short collars, range 2, with installed on bottom, It is set to a depth of 793 ft. in diam. hole. 2. Cementing was done by Denton Cementing of Artesia, New Mex. plug method. 155 sacks of class C compart wards in the same set to a same set	a 796 ft., $6\frac{1}{2}$ inch using the pump and
 6-25-84 Cemented casing string 6-30-84 Pressure tested casing string Casing is 4¹/₂, 9.51b., 8rd thread, short collars, range 2, with installed on bottom, It is set to a depth of 793 ft. in diam. hole. Cementing was done by Denton Cementing of Artesia, New Mex. plug method. 155 sacks of class C cement were used and to the bottom. A wire line measuring demined and the set to the bottom. 	a 796 ft., $6\frac{1}{2}$ inch using the pump and then the pig pushed
 6-25-84 Cemented casing string 6-30-84 Pressure tested casing string Casing is 4¹/₂, 9.51b., 8rd thread, short collars, range 2, with installed on bottom, It is set to a depth of 793 ft. in diam. hole. Cementing was done by Denton Cementing of Artesia, New Mex. plug method. 155 sacks of class C cement were used and to the bottom. A wire line measuring demined and the set to the bottom. 	a 796 ft., $6\frac{1}{2}$ inch using the pump and then the pig pushed
 6-25-84 Cemented casing string 6-30-84 Pressure tested casing string Casing is 4¹/₂, 9.51b., 8rd thread, short collars, range 2, with installed on bottom, It is set to a depth of 793 ft. in diam. hole. Cementing was done by Denton Cementing of Artesia, New Mex. plug method. 155 sacks of class C cement were used and to the bottom. A wire line measuring device was used to pig was on bottom. After the cement set wineline measure. 	a 796 ft., $6\frac{1}{2}$ inch b using the pump and then the pig pushed b determine that the
 6-25-84 Cemented casing string 6-30-84 Pressure tested casing string Casing is 4¹/₂, 9.51b., 8rd thread, short collars, range 2, winstalled on bottom, It is set to a depth of 793 ft. in diam. hole. Cementing was done by Denton Cementing of Artesia, New Mex. plug method. 155 sacks of class C cement were used and to the bottom. A wire line measuring device was used to pig was on bottom. After the cement set, wireline was used to cement had filled the annulus of the bolo test. 	a 796 ft., $6\frac{1}{2}$ inch , using the pump and then the pig pushed , determine that the sed to determine that
 6-25-84 Cemented casing string 6-30-84 Pressure tested casing string Casing is 4¹/₂, 9.51b., 8rd thread, short collars, range 2, with installed on bottom, It is set to a depth of 793 ft. in diam. hole. Cementing was done by Denton Cementing of Artesia, New Mex. plug method. 155 sacks of class C cement were used and to the bottom. A wire line measuring device was used to pig was on bottom. After the cement set, wireline was use cement had filled the annulus of the hole to 59 feet from 3. Since the cement was in place for 5 down before it. 	a 796 ft., $6\frac{1}{2}$ inch using the pump and then the pig pushed determine that the sed to determine that om the surface.
 6-25-84 Cemented casing string 6-30-84 Pressure tested casing string Casing is 4¹/₂, 9.51b., 8rd thread, short collars, range 2, winstalled on bottom, It is set to a depth of 793 ft. in diam. hole. Cementing was done by Denton Cementing of Artesia, New Mex. plug method. 155 sacks of class C cement were used and to the bottom. A wire line measuring device was used to pig was on bottom. After the cement set, wireline was use cement had filled the annulus of the hole to 59 feet from Bottled nitrogen was used to proceed to the cement was in place for 5 days before testing, or Bottled nitrogen was used to proceed to the cement was used to play before testing. 	a 796 ft., $6\frac{1}{2}$ inch using the pump and then the pig pushed determine that the sed to determine that on the surface. tion 1 applies.
 6-25-84 Cemented casing string 6-30-84 Pressure tested casing string Casing is 4¹/₂, 9.51b., 8rd thread, short collars, range 2, winstalled on bottom, It is set to a depth of 793 ft. in diam. hole. Cementing was done by Denton Cementing of Artesia, New Mex. plug method. 155 sacks of class C cement were used and to the bottom. A wire line measuring device was used to pig was on bottom. After the cement set, wireline was use cement had filled the annulus of the hole to 59 feet from Bottled nitrogen was used to proceed to the cement was in place for 5 days before testing, or Bottled nitrogen was used to proceed to the cement was used to place for 5 days before testing, or bottled nitrogen was used to proceed to the cement was used to place for 5 days before testing, or bottled nitrogen was used to proceed to the cement was used to place for 5 days before testing, or bottled nitrogen was used to proceed to the cement was used to place for 5 days before testing. 	a 796 ft., $6\frac{1}{2}$ inch using the pump and then the pig pushed determine that the sed to determine that on the surface. otion 1 applies.
 6-25-84 Cemented casing string 6-30-84 Pressure tested casing string Casing is 4¹/₂, 9.51b., 8rd thread, short collars, range 2, with installed on bottom, It is set to a depth of 793 ft. in diam. hole. Cementing was done by Denton Cementing of Artesia, New Mex. plug method. 155 sacks of class C cement were used and to the bottom. A wire line measuring device waw used to pig was on bottom. After the cement set, wireline was used to cement had filled the annulus of the hole to 59 feet from Bottled nitrogen was used to pressurize the caseing to 60 minute test was 600 minute test was 600	a 796 ft., $6\frac{1}{2}$ inch using the pump and then the pig pushed determine that the sed to determine that on the surface. otion 1 applies.
 6-25-84 Cemented casing string 6-30-84 Pressure tested casing string Casing is 4¹/₂, 9.51b., 8rd thread, short collars, range 2, with installed on bottom, It is set to a depth of 793 ft. in diam. hole. Cementing was done by Denton Cementing of Artesia, New Mex. plug method. 155 sacks of class C cement were used and to the bottom. A wire line measuring device was used to pig was on bottom. After the cement set, wireline was use cement had filled the annulus of the hole to 59 feet from 3. Since the cement was in place for 5 down before it. 	a 796 ft., $6\frac{1}{2}$ inch using the pump and then the pig pushed determine that the sed to determine that on the surface. otion 1 applies.
 6-25-84 Cemented casing string 6-30-84 Pressure tested casing string Casing is 4¹/₂, 9.51b., 8rd thread, short collars, range 2, with installed on bottom, It is set to a depth of 793 ft. in diam. hole. Cementing was done by Denton Cementing of Artesia, New Mex. plug method. 155 sacks of class C cement were used and to the bottom. A wire line measuring device waw used to pig was on bottom. After the cement set, wireline was used to cement had filled the annulus of the hole to 59 feet from Bottled nitrogen was used to pressurize the caseing to 60 minute test was 600 minute test was 600	a 796 ft., $6\frac{1}{2}$ inch using the pump and then the pig pushed determine that the sed to determine that on the surface. otion 1 applies.
 6-25-84 Cemented casing string 6-30-84 Pressure tested casing string Casing is 4¹/₂, 9.51b., 8rd thread, short collars, range 2, with installed on bottom, It is set to a depth of 793 ft. in diam. hole. Cementing was done by Denton Cementing of Artesia, New Mex. plug method. 155 sacks of class C cement were used and to the bottom. A wire line measuring device waw used to pig was on bottom. After the cement set, wireline was used to cement had filled the annulus of the hole to 59 feet from Bottled nitrogen was used to pressurize the caseing to 60 minute test was 600 minute test was 600	a 796 ft., $6\frac{1}{2}$ inch using the pump and then the pig pushed determine that the sed to determine that on the surface. otion 1 applies.
 6-25-84 Cemented casing string 6-30-84 Pressure tested casing string Casing is 4¹/₂, 9.51b., 8rd thread, short collars, range 2, winstalled on bottom, It is set to a depth of 793 ft. in diam. hole. Cementing was done by Denton Cementing of Artesia, New Mex. plug method. 155 sacks of class C cement were used and to the bottom. A wire line measuring device waw used to pig was on bottom. After the cement set, wireline was used to cement had filled the annulus of the hole to 59 feet from Bottled nitrogen was used to pressurize the caseing to 60 minute test was 600 min	a 796 ft., $6\frac{1}{2}$ inch using the pump and then the pig pushed determine that the sed to determine that on the surface. otion 1 applies.
 6-25-84 Cemented casing string 6-30-84 Pressure tested casing string Casing is 4¹/₂, 9.51b., 8rd thread, short collars, range 2, winstalled on bottom, It is set to a depth of 793 ft. in diam. hole. Cementing was done by Denton Cementing of Artesia, New Mex. plug method. 155 sacks of class C cement were used and to the bottom. A wire line measuring device was used to pig was on bottom. After the cement set, wireline was use cement had filled the annulus of the hole to 59 feet from Bottled nitrogen was used to pressurize the caseing to 6 pressure at the end of the 30 minute test was 600 psi 	a 796 ft., $6\frac{1}{2}$ inch using the pump and then the pig pushed determine that the sed to determine that on the surface. otion 1 applies.
 6-25-84 Cemented casing string 6-30-84 Pressure tested casing string Casing is 4¹/₂, 9.51b., 8rd thread, short collars, range 2, winstalled on bottom, It is set to a depth of 793 ft. in diam. hole. Cementing was done by Denton Cementing of Artesia, New Mex. plug method. 155 sacks of class C cement were used and to the bottom. A wire line measuring device waw used to pig was on bottom. After the cement set, wireline was used to cement had filled the annulus of the hole to 59 feet from Bottled nitrogen was used to pressurize the caseing to 60 minute test was 600 min	a 796 ft., $6\frac{1}{2}$ inch using the pump and then the pig pushed determine that the sed to determine that on the surface. otion 1 applies.
 6-25-84 Cemented casing string 6-30-84 Pressure tested casing string Casing is 4¹/₂, 9.51b., 8rd thread, short collars, range 2, winstalled on bottom, It is set to a depth of 793 ft. in diam. hole. Cementing was done by Denton Cementing of Artesia, New Mex. plug method. 155 sacks of class C cement were used and to the bottom. A wire line measuring device waw used to pig was on bottom. After the cement set, wireline was use cement had filled the annulus of the hole to 59 feet from Bottled nitrogen was used to pressurize the caseing to 6 pressure at the end of the 30 minute test was 600 psi 	a 796 ft., $6\frac{1}{2}$ inch using the pump and then the pig pushed determine that the sed to determine that on the surface. otion 1 applies.
 6-25-84 Cemented casing string 6-30-84 Pressure tested casing string Casing is 4¹/₂, 9.51b., 8rd thread, short collars, range 2, winstalled on bottom, It is set to a depth of 793 ft. in diam. hole. Cementing was done by Denton Cementing of Artesia, New Mex. plug method. 155 sacks of class C cement were used and to the bottom. A wire line measuring device was used to pig was on bottom. After the cement set, wireline was used to grig was on bottom. After the cement set, wireline was used to pig was on bottom. After the cement set, wireline was used to grig was in place for 5 days before testing, or Bottled nitrogen was used to pressurize the caseing to 6 pressure at the end of the 30 minute test was 600 psi show a zero % drop in pressure. 	a 796 ft., $6\frac{1}{2}$ inch , using the pump and then the pig pushed b) determine that the sed to determine that om the surface. tion 1 applies. 00 psi The The results of test
 6-25-84 Cemented casing string 6-30-84 Pressure tested casing string Casing is 4¹/₂, 9.51b., 8rd thread, short collars, range 2, winstalled on bottom, It is set to a depth of 793 ft. in diam. hole. Cementing was done by Denton Cementing of Artesia, New Mex. plug method. 155 sacks of class C cement were used and to the bottom. A wire line measuring device was used to pig was on bottom. After the cement set, wireline was use cement had filled the annulus of the hole to 59 feet from Bottled nitrogen was used to pressurize the caseing to 6 pressure at the end of the 30 minute test was 600 psi 	a 796 ft., $6\frac{1}{2}$ inch using the pump and then the pig pushed determine that the sed to determine that on the surface. otion 1 applies.
 6-25-84 Cemented casing string 6-30-84 Pressure tested casing string Casing is 4¹/₂, 9.51b., 8rd thread, short collars, range 2, we installed on bottom, It is set to a depth of 793 ft. in diam. hole. Cementing was done by Denton Cementing of Artesia, New Mex. plug method. 155 sacks of class C cement were used and to the bottom. A wire line measuring device was used to pig was on bottom. After the cement set, wireline was used to give as on bottom. After the cement set, wireline was used to pig was on bottom. After the cement set, wireline was used to pressure at the end of the 30 minute test was 600 psi show a zero % drop in pressure. 	a 796 ft., $6\frac{1}{2}$ inch , using the pump and then the pig pushed b) determine that the sed to determine that om the surface. tion 1 applies. 00 psi The The results of test

-	•	
DITIONS	OF	APPROVAL, IF ANY:

7-10-84 DATE ____

4