

Well file

OIL CONSERVATION COMMISSION  
P. O. BOX 871  
SANTA FE, NEW MEXICO

INSPECTION REPORT

MARCH 4, 1954

C  
O  
P  
Y

SWEETMAN & ADAY  
DRILLING ASSOCIATES

RE: Cecil D'Spain #1  
NENW Sec. 12-6N-6E  
Torrance County

Today I visited this well and found same shut down with no activity on the lease. From Mr. W. M. Parnall, partner and driller, I learned that following the casing job of February 9, they allowed the cement to set for a little over two weeks. Then they went in with clean-out tools and got down to 36' off bottom of the casing and found that water was coming in. They therefore did not attempt to drill out the cement plug. A bad spot in the 6" string was found at 1014'. A homemade bridging plug was run below this depth and 200 sacks of cement were spotted at this break. The operator estimated that 165 sacks went behind the casing through the break leaving 35 sacks inside the pipe.

The status of the well today is: shut down, waiting on cement for water shut off.

EAC

EUGENE A. CHAVEZ,  
Oil & Gas Inspector  
District #4