## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office		1	1107204 1 1 07
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION		WELL API NO.
DISTRICT II	P.O.Box 208 Santa Fe, New Mexico 8		30-059-20054
P.O. Drawer DD, Artesia, NM 88210	Santa re, New Mexico a	8/304-2088	5. Indicate Type of Lease
DISTRICT III			STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
SUNDRY NOT	ICES AND REPORTS ON V	WELLS	
(DO NOT USE THIS FORM FOR PRODIFFERENT RESER	OPOSALS TO DRILL OR TO DEEP VOIR. USE "APPLICATION FOR	PEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
(FORM C	-101) FOR SUCH PROPOSALS.)	I EGGANT	
1. Type of Well OIL GAS GAS			-
WELL WELL	OTHER	C02	BDCDGU - 1934
Name of Operator     Amoco Production Company			8. Well No.
3. Address of operator			101
PO Box 606, Clayto	n NM 88415		9. Pool name or Wildeat
4. Well Location			Tubb
Unit Letter J: 1930	Feet From The South	Line and 1987	Feet From The East Line
Section 10	Township 19N I	Range 34E N	MPM Union County
	10. Elevation (Show when	her DF, RKB, RT, GR, etc.)	
11. Chack App		L	
Спеск Арр	ropriate Box to Indicate 1	1	
NOTICE OF INT	ENTION TO:	SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	DPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEN	MENT JOB
OTHER:	OTHER: Install casing liner		
12. Describe Proposed or Completed Opera	itions (Clearly state all pertinent deta		icluding estimated date of starting any proposed
work.) SEE RULE 1103.		,	
	√° >	<b>x</b>	
	$O_{C_{i}}$		
1. MIRUSU 02/15/96		11 Flow well am and	(0.1
2. Run 1.625 blanking plug		11. Flow well up casing 68 days 12. MIRUSU 04/30/96	
3. Nipple up BOP		13. Kill well	
4. Lay down 2 7/8 fiberglass tbg		14. Run tailpipe, pkr, & fiberglass tbg	
5. Run 2 7/8 steel tbg		15. TLA 2151', pkr set at 2121'	
<ul><li>6. Rig up snubbing unit</li><li>7. Snub 2 7/8 tbg, pkr, and tailpipe out of well</li></ul>		16. Nipple down BOP	
8. Rig down snubbing unit		17. Pressure test csg & pkr 500 PSI - OK 18. Flow well to tank	
9. Return well to production thru 5 1/2 csg		19. Return well to production	
10. RDMOSU 02/21/96		20. RDMOSU 05/01/9	96
I hereby certify that the information above	is true and corpelete to the best of my	y knowledge and belief.	
SIGNATURE BILLY E.	Fribal .	ma Field Forem	nan
TYPE OR PRINT NAME Billy E Pr			TELEPHONE NO. 374-305
(This space for State Use)	. 0		2,4-30
12.90		DISTRICT CH	DEDIMOR -/-/s
APPROVED BY 19 CM	TUNIO T	mre	PERVISOR DATE 5/20/96
CONDITIONS OF APPROVAL, IF ANY:			DATE