

INCLINATION REPORT (One Copy Must Be Filed With Each Completion Report.)		
1. FIELD NAME	2. LEASE NAME	Well Number
	Bravo Dome Carbon Dioxide Gas Unit	1834-291 G
3. OPERATOR AMOCO Production Co.		
4. ADDRESS P.O. Box 606, Clayton, N.M. 88415		County
5. LOCATION T18N R 34E, Sec 29 "G"		

[illegible]

17. Is any information shown on the reverse side of this form? ☐ yes ☒ no

18. Accumulative total displacement of well bore at total depth of 2796 feet = 24.25 feet.

\*19. Inclination measurements were made in — ☐ Tubing ☐ Casing ☐ Open hole ☒ Drill Pipe

20. Distance from surface location of well to the nearest lease line \_\_\_\_\_ feet.

21. Minimum distance to lease line as prescribed by field rules \_\_\_\_\_ feet.

22. Was the subject well at any time intentionally deviated from the vertical in any manner whatsoever? No

(If the answer to the above question is "yes", attach written explanation of the circumstances.)

Drilling Contractor Baker & Taylor Drilling Co.

By David P. Myers

Subscribed and sworn to before me this 5th day of November 1984



**SUE BAER**  
Notary Public, State of Texas  
My Commission Expires 6/9/19 88

She Baer  
Notary Public

My Commission Expires:

Potter County, Texas