

INCLINATION REPORT


Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2232-251G Field: Bravo Dome

Location: 1955' FEL X 1998' FNL T22N R320E SEC 25 UNIT G

DEPTH	ANGLE INCLINATION DEGREES
<u>345'</u>	<u>1/2°</u>
<u>450'</u>	<u>3/4°</u>
<u>680'</u>	<u>3/4°</u>
<u>1118'</u>	<u>1°</u>
<u>1592'</u>	<u>1°</u>
<u>2104'</u>	<u>1°</u>
<u>2460'</u>	<u>1 1/4°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.




Title: SITCON Tool Pusher