

OIL CONSERVATION DIVISION
RECEIVED

93 JUL 7 AM 8 52

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. ²²³³⁻3016 Field: Bravo Dome

Location: 2003' FEL X 2019' FNL, T22N, R33E, SEC 30, UNIT 6

<u>DEPTH</u>	<u>ANGLE INCLINATION DEGREES</u>
<u>404</u>	<u>3/4</u>
<u>700</u>	<u>1</u>
<u>1173</u>	<u>1 1/4</u>
<u>1670</u>	<u>1 1/4</u>
<u>2160</u>	<u>1 1/4</u>
<u>2529</u>	<u>1</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Ronnie R. Cam

Kurt Stelmings
Title: Area Toolpusher

93 JUL 7 AM 8 52
OIL CONSERVATION DIVISION
RECEIVED