

## INCLINATION REPORT

CONCEPT DIVISION  
RECEIVED

03 JUN 74 AM 9 21

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2233-311 J Field: Bravo DomeLocation: 1982' FELX 1988' FSL, T22N, R32E, SEC31, UNIT J

<u>DEPTH</u>	<u>ANGLE</u> <u>INCLINATION DEGREES</u>
<u>418'</u>	<u>1/2°</u>
<u>681'</u>	<u>1/4°</u>
<u>1181'</u>	<u>1/2°</u>
<u>1674'</u>	<u>3/4°</u>
<u>2173'</u>	<u>3/4°</u>
_____	_____

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Larry J. Young (Amoco)Kurt Stahmer  
Title: Area Toolpusher