

INCLINATION REPORT

RECEIVED IN DIVISION
RECEIVED

93 JUN 17 007 8 56

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2233-351 Field: Bravo Dome

Location: 1955' Fw L X 1992' Fw L, T22N, R33E, Sec 35, Unit F

<u>DEPTH</u>	<u>ANGLE</u> <u>INCLINATION DEGREES</u>
<u>245'</u>	<u>$3/4^{\circ}$</u>
<u>461'</u>	<u>$1/2^{\circ}$</u>
<u>709</u>	<u>$1/4^{\circ}$</u>
<u>1152</u>	<u>$3/4^{\circ}$</u>
<u>1626</u>	<u>$1 3/4^{\circ}$</u>
<u>1932</u>	<u>$1 1/2^{\circ}$</u>
<u>2426</u>	<u>$1 1/2^{\circ}$</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Sammy J. Young

Bob D. Dandy
Title: SITTON TOOL PUSHER