


Oxy USA, Inc.-Bravo Dome  
P.O. Box 4294  
Houston, Texas 77210-4294


Bravo Dome Unit #1935-0520  
Union County, NM

|      |       |       |      |       |       |
|------|-------|-------|------|-------|-------|
| 517  | 5.17  | 3/4   | 1.31 | 6.79  | 6.79  |
| 730  | 7.30  | 1     | 1.75 | 12.78 | 12.78 |
| 1287 | 12.87 | 1 1/2 | 2.63 | 33.78 | 33.78 |
| 1785 | 17.85 | 1 1/2 | 2.63 | 46.86 | 46.86 |
| 2283 | 22.83 | 1 1/2 | 2.63 | 59.93 | 59.93 |
| 2348 | 23.48 | 1 1/2 | 2.63 | 61.64 | 61.64 |

  
\_\_\_\_\_  
Michael Roghair - General Manager

The attached instrument was acknowledged before me on the 25<sup>th</sup> day of  
October, 2002 by Michael Roghair - General Manager, CapStar Drilling, Inc.



  
\_\_\_\_\_  
Notary Public