## OIL CONSERVATION COMMISSION P. O. BOX 871 SANTA FE, NEW MEXICO

## INSPECTION REPORT May 21, 1952

HARRY C. LONG

Re: Dalies No. 1 (formerly Sunol No. 1) Sec. 32-7N-1E Valencia County

On this day I inspected the above captioned well to check on the final work done by the H. C. Long crews following last week's plugging job. The 10 5/8" surface casing had been cemented at the surface and a regulation metal marker was placed in the hole. This marker however, was not in very solidly, indicating that the surface plug sank before the marker was placed or no cement at all was used around the marker. The cellar was left exposed so that approximately eight feet of marker pipe extends above the casing. The mud pits were half full of water and no effort has been made to cover same.

H. C. Long has taken all of his drill pipe and other sundry equipment which was of necessity furnished by himself to ready the rig prior to deepening. The derrick, draw-works, mud pump, tubular goods and other equipment left on location belongs to the Sunol Oil Company.

On May 19th, the Sunol Oil Company, plaintiff, and Harry C. Long and Orris R. Hedges, defendants in Cause No. 6363, at Los Lunas, New Mexico, reached an agreement to settle all controversies in this matter in such a way as to conform with the Rules and Regulations of the Oil Conservation Commission. All conditions are to be met within a period of fifteen days from above date.

E. A. CHAVEZ, Geologiet - District 4