




NAVJO REFINING COMPANY
ARTESIA REFINERY, EDDY COUNTY, NEW MEXICO
2011 ANNUAL GROUNDWATER REPORT

**DRO CRITICAL GROUNDWATER
SCREENING LEVEL EXCEEDANCE AREAS
FIRST SEMIANNUAL EVENT 2011**

FIGURE
9

ARCADIS

0 800 1600 2400 3200 Feet
GRAPHIC SCALE

LEGEND:
DRO GROUNDWATER EXCEEDANCE AREA
MONITORING WELL
RECOVERY WELL
IRRIGATION WELL
ABANDONED WELL

New Mexico