

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Cimarex Energy	Contact Christine Alderman	
Address 600 N Marienfeld Ste 600 Midland TX	Telephone No. 432-853-7059	
Facility Name Red Hills SWD #1	Facility Type SWD	
Surface Owner	Mineral Owner	API No. 30-025-35598

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	28	25S	33E	660	s	660	W	Lea

Latitude 32.09614 Longitude -103.58256

NATURE OF RELEASE

Type of Release produced water	Volume of Release 330 bbls	Volume Recovered 270 bbls
Source of Release tri plex pump	Date and Hour of Occurrence 03/29/2015	Date and Hour of Discovery 03/29/2015 12:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Doc Oberding/Sol Hughes	
By Whom? Christine Alderman	Date and Hour 03/30/15 11:00am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD; Dr. Oberding at 12:07 pm, Apr 08, 2015

Describe Cause of Problem and Remedial Action Taken.*

The fiberglass line coming off the fiberglass water storage tank snapped off at the connection.

Describe Area Affected and Cleanup Action Taken.*

119' x 68' bermed containment. An environmental consultant will assess and prepare work plan.

Added to original RP 3506

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Christine Alderman	OIL CONSERVATION DIVISION	
Printed Name: Christine Alderman	Hydrologist Approved by Environmental Specialist	
Title: ESH Supervisor	Approval Date: 04/08/2015	Expiration Date: 07/08/2015
E-mail Address: calderman@cimarex.com	Conditions of Approval: Remediate and delineate as per NMOCD guides.	Attached <input type="checkbox"/> 1RP-3506
Date: 3/30/2015	Phone: 432-853-7059	

* Attach Additional Sheets If Necessary

Incident added to 1RP-3506.

nTO1501548835

pTO1501549006