

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Cimarex Energy	Contact	Christine Alderman
Address	600 N Marienfeld Ste 600 Midland TX	Telephone No.	432-853-7059
Facility Name	Shell D State Com 13	Facility Type	production

Surface Owner	Mineral Owner	API No.	30-025-31684
---------------	---------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	36	21S	36E	1780	S	760	W	Lea

Latitude 32.4329 Longitude -103.2249

NATURE OF RELEASE

Type of Release	crude oil and produced water	Volume of Release	167 bbls oil/ 20 bbls PW	Volume Recovered	160 bbls oil/ 15 bbls PW
Source of Release	tank	Date and Hour of Occurrence	4/7/2015	Date and Hour of Discovery	4/7/2015
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Doc Oberding		
By Whom?	Gloria Garza	Date and Hour	4/8/2015 10:53 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD; Dr. Oberding at 3:49 pm, Apr 20, 2015

Describe Cause of Problem and Remedial Action Taken.*

While trying to unload tank into haul truck, the hauler tried to remove the bull plug off the valve and the reducing swedge broke off the fiberglass tank and released fluids into unlined containment.

Describe Area Affected and Cleanup Action Taken.*

All fluids contained in unlined containment. Consulting company will assess, delineate and submit workplan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Christine Alderman</i>	OIL CONSERVATION DIVISION	
Printed Name: Christine Alderman	Hydrologist	Approved by Environmental Specialist: <i>[Signature]</i> PhD
Title: ESH Supervisor	Approval Date: 04/20/2015	Expiration Date: 07/20/2015
E-mail Address: calderman@cimarex.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/17/2015 Phone: 432-853-7059	Site samples required. Delineate and remediate area as per NMOCD guides. Provide geotagged photographs of remediation.	1RP-3615 162683

* Attach Additional Sheets If Necessary

nTO1511057106

pTO1511057296