

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

By OCD; Dr. Oberding at 3:21 pm, Jun 05, 2015

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company <i>Mas Operating Company</i>	Contact <i>Brooke Makowsky</i>
Address <i>P.O. Box 52167, Midland, TX 79710</i>	Telephone No. <i>432/618-0678</i>
Facility Name <i>B.V. Lynch A #7</i>	Facility Type <i>Flowline</i>

Surface Owner <i>Federal/Private</i>	Mineral Owner <i>Federal</i>	API No. <i>30-025-02509</i>
--------------------------------------	------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section <i>35</i>	Township <i>20S</i>	Range <i>34E</i>	Feet from the <i>1650</i>	North/South Line <i>South Line</i>	Feet from the <i>990</i>	East/West Line <i>West Line</i>	County <i>Lea County, NM</i>
-------------	----------------------	------------------------	---------------------	------------------------------	---------------------------------------	-----------------------------	------------------------------------	---------------------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release <i>Produced water spilled</i>	Volume of Release <i>30 bbls.</i>	Volume Recovered <i>10 bbls wtr. 1 bbl oil</i>
Source of Release <i>fuse on broken flowline</i>	Date and Hour of Occurrence <i>7-12-14 - 1:00 PM</i>	Date and Hour of Discovery <i>7-12-14 - 1:00 PM</i>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Truck ran over flowline and broke the fuse loose, spilled 30 bbls of water and 1 bbl of oil. Vacuum truck was there within a few hours and was able to pick up fluid.

Describe Area Affected and Cleanup Action Taken.*

Safety & Environmental Solutions, Inc. will delineate the site and submit the appropriate work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Brooke Makowsky</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Brooke Makowsky</i>	Hydrologist	Approved by Environmental Specialist: <i>[Signature]</i> P&O
Title: <i>Field Admin.</i>	Approval Date: <i>06/05/2015</i>	Expiration Date: <i>09/05/2015</i>
E-mail Address: <i>masoperating@att.net</i>	Conditions of Approval: <i>Site samples required. Delineate and remediate area as per NMOCD guides.</i>	Attached <input type="checkbox"/>
Date: <i>4-7-2015</i> Phone: <i>432/618-0678</i>	<i>Provide geotagged photo documentation of remediation.</i>	<i>IRP-3662 267077</i>

* Attach Additional Sheets If Necessary

nTO1515655708

pTO1515655980