State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

Ken McQueen Cabinet Secretary **David R. Catanach, Division Director**Oil Conservation Division



Matthias Sayer Deputy Cabinet Secretary

20 April 2017

Michael L. Meyer, P.G., Senior Project Manager Terracon 4905 Hawkins NE Albuquerque, NM 87109

Re: Closure and No Further Action Required

Facility: Former Weatherford Facility, 5432 Highway 64, Farmington, New Mexico

San Juan County, E-19-29N-12W, GW-126

Ref: http://ocdimage.emnrd.state.nm.us/Imaging/AEOrderFileView.aspx?appNo=pENV000GW00137

Dear Mr. Meyer:

The Oil Conservation Division (OCD) has reviewed the reports available in the OCD Online Imaging website referenced above. The most relevant document is summarized below.

14Feb92 Buys & Assoc Addendum Site Remediation Closure Report HOMCO International Inc, Location 151 Facility, Farmington, New Mexico describes sampling and cleanup activities done in 1991. Soil sample results from excavation work on site showed compliance with OCD soil cleanup guidelines for total petroleum hydrocarbons and aromatic hydrocarbons (BTEX). Some contaminated soil remained which was covered by a concrete cap which prevents migration of hydrocarbons. Groundwater in the area was thought to be less than 50 feet below surface at that time. The report recommended that no further excavation or remedial action was required.

I concur with this recommendation and no further corrective action is required. This finding by the OCD does not relieve the landowner of responsibility if future information shows a threat to ground water, surface water, human health, or the environment. Further, it does not relieve the landowner of responsibility for compliance with any federal, state, or local law. If you have additional questions, please feel free to call.

Sincerely,

Randolph Bayliss, P.E. Hydrologist 505-476-3084

cc: Jim Griswold, Charlie Perrin, Brandon Powell, Vanessa Fields, Cory Smith