

## Rose-Coss, Dylan H, EMNRD

---

**From:** Rose-Coss, Dylan H, EMNRD  
**Sent:** Thursday, June 20, 2019 3:24 PM  
**To:** 'Christine Alderman'; Amos, James A (jamos@blm.gov)  
**Subject:** RE: Red Hills Unit 17H (30-025-42325)

All,

The NMOCD tracking number for this release is 1RP-5559.

Thanks,

**Dylan Rose-Coss**

*Environmental Scientist*  
Oil Conservation Division  
1220 South St. Francis Drive  
Santa Fe, New Mexico 87505

(505) 476-3488

---

**From:** Christine Alderman <calderman@cimarex.com>  
**Sent:** Friday, June 7, 2019 2:22 PM  
**To:** Amos, James A (jamos@blm.gov) <jamos@blm.gov>; EMNRD-OCD-District1spills <EMNRD-OCD-District1spills@state.nm.us>  
**Subject:** [EXT] Red Hills Unit 17H (30-025-42325)

All,

We had a produced water release at the above named location. A ¼" ball valve was inadvertently left open and the release measured 35' x 23' x 5" on the location pad. It was in and around piping and pumps. The impacted soils were hand dug to remove the heavily impacted soils. Samples will be collected to determine the impact left to remove, if any. The volume was determined from pumpers numbers and a spill calculation spreadsheet.

I am attaching the C-141.

Respectfully,

Christine Alderman

Cimarex Energy Co.



ESH Supervisor – Permian Basin  
Midland TX  
Cell – 432.853.7059