

1R - 182

**GENERAL
CORRESPONDENCE**

YEAR(S):

1997

MOBIL PIPELINE COMPANY
P.O. BOX 670
SEMINOLE, TEXAS 79360

B. H. Olson

State of New Mexico
Oil Conservation Division
P.O. BOX 1980
HOBBS NEW MEXICO 88240

SPILL REPORTED: 3-27-97
SEC. 2- T10S - R35E
LEA COUNTY
MOBIL LEAK # 307-97-035

JUL 28 1997

e

In accordance with Rule 116 the above referenced leak site has been cleaned through In-Situ remediation to TPH levels below the action levels required.

Attached is the final test results from the site. The sample is an aggregate test of the site and the analysis was performed by an independent third party using field test equipment.

Please review the site and notify me at 915-686-1466 if any other action is deemed necessary.

Sincerely,

J.M. Hill

CC. Hobbs NMOC

9/16/97
Referred to Hobbs Office
for approval
Will Olson

6701 Aberdeen Avenue
Lubbock, Texas 79424
806•794•1296
FAX 806•794•1298

ANALYTICAL RESULTS FOR
RE ENVIRONMENTAL
Attention: Tommy Stewart
1599 W. 300
Levelland, TX 79336

June 26, 1997
Receiving Date: 06/20/97
Sample Type: Soil
Project No: NA
Project Location: Crossroads Station

Prep Date: 06/23/97
Analysis Date: 06/23/97
Sampling Date: 06/20/96
Sample Condition: I & C
Sample Received by: JH
Project Name: NA

TA#	FIELD CODE	IGNITABILITY
	CROSSROADS STATION	
T75905	Bottom Hole	Nonignitable
T75906	Remediated Pile	Nonignitable
RPD		0

METHODS: EPA SW 846-2.1.1.
CHEMIST: JT



Director, Dr. Blair Leftwich

6-26-97

DATE


TRACE ANALYSIS, INC.

A Laboratory for Advanced Environmental Research and Analysis

6001 Ashcroft Avenue

Labback 794-794-794

904-794-1286

FAX 803-794-298

ANALYTICAL RESULTS FOR

RE Environmental

Attention Tommy Stewart

1599 W 300

Levelland

Tx 79336

Lab Receiving #: 9706000366

Date Rec: 6/20/97

Sampling Date: 6/20/97

Sample Condition: Intact and Cool

Sample Received By: JH

Date: Jun 25, 1997

Project: N/A

Proj Name: N/A

Proj Loc: Crossroads Station

TP#	Field Code	MATRIX	MTBE (mg/Kg)	BENZENE (mg/Kg)	TOLUENE (mg/Kg)	ETHYL- BENZENE (mg/Kg)	M,P,O XYLENE (mg/Kg)	TOTAL BTX (mg/Kg)
T75905	Bottom Hole	Soil	<0.050	<0.050	<0.050	<0.050	0.105	0.105
T75906	Remediated Pile	Soil	<0.050	<0.050	<0.050	<0.050	0.110	0.110
QC			0.091	0.093	0.092	0.090	0.289	
RPD			9	9	9	9	10	
% Extraction Accuracy			93	99	99	98	105	
% Instrument Accuracy			91	93	92	90	96	

Reporting Limit:

0.05 0.05 0.05 0.05 0.05 0.05

TEST	PREP METHOD	PREP DATE	ANALYSIS METHOD	ANALYSIS COMPLETED	CHEMIST	QC: (mg/L)	SPIKE: (mg/Kg)
MTBE/BTEX	EPA 5030	6/24/97	EPA 8020	6/24/97	AG	0.100 ea	5 ea


Director, Dr. Blair Leftwich

Date

6-25-97

R.E. ENVIRONMENTAL SERVICES INC.

P.O. BOX 1376 LEVELLAND TX, 79336-1376 (806) 894-1656



MOBIL PIPE LINE CROSSROADS STATION

HYDROCARBON TEST RESULTS

TEST POINTS	BOTTOM RESULTS	REMEDIATED RESULTS
1.	745ppm @ 6'	815ppm
2.	820ppm @ 6'	785ppm
3.	687ppm @ 4'	830ppm

R.E. ENVIRONMENTAL SERVICES INC.
P.O. BOX 1376 Levelland TX, 79336- (806) 894-1656

CUSTOMER: MOBIL PIPE LINE

LOCATION: CROSSROADS STATION

INVOICE #: 6040

MOBIL LEAK: CROSSROADS STATION #1

DATE STARTED: 6-16-97

DATE COMPLETED: 6-20-97

TOTAL CU. YDS.: 1483.2

TOTAL COST: \$5,113.00

COST PER CU. YD.: \$3.45