


**1R - 427 - 122**

# **REPORTS**

**DATE:**

**1-2-2001**



427-122

### RICE OPERATING COMPANY JUNCTION BOX FINAL REPORT

#### BOX LOCATION

SWD SYSTEM	JUNCTION	UNIT	SECTION	TOWNSHIP	RANGE	COUNTY	BOX DIMENSIONS - FEET		
							Length	Width	Depth
EME	V-5	V	5	21S	36E	LEA	4'	4'	3'

LAND TYPE: \_\_\_\_\_ STATE X FEE LANDOWNER \_\_\_\_\_ OTHER \_\_\_\_\_

Depth to Groundwater 150'-200' feet NMOCD SITE ASSESSMENT RANKING SCORE: 0

Date Started 01/02/2001 Date Completed 01/02/2001 OCD Witness NONE

Soil Excavated 12 cubic yards Excavation length 8' Width 8' Depth 8' feet

Soil Disposed 12 cubic yards Offsite Facility Sundance Disposal Facility location Eunice, NM

FINAL ANALYTICAL RESULTS: **Sample Date** January 2, 2001 **Sample Depth** 8' bgs

Procure 5-point composite sample of bottom and 4-point composite sample of sidewalls. TPH, BTEX and Chloride laboratory test results completed by using an approved lab and testing procedures pursuant to NMOCD guidelines.

Sample Location	Benzene mg/kg	Toluene mg/kg	Ethyl Benzene mg/kg	Total Xylenes mg/kg	GRO mg/kg	DRO mg/kg	Chlorides mg/kg
SIDEWALLS	<0.002	<0.002	<0.002	<0.006	<50	95.6	596
BOTTOM	<0.002	<0.002	<0.002	<0.006	<50	1220	116

General Description of Remedial Action: The junction box was removed from the main line. The main line is still active. All impacted soil was hauled off to the Sundance disposal facility and replaced with clean backfill. A compact clay barrier was installed followed by a junction box then backfilled.  
All results did not exceed the NMOCD guidelines. Natural attenuation will remediate the remaining hydrocarbons.

#### CHLORIDE FIELD TESTS

LOCATION	DEPTH	Cl
SIDEWALLS	4'-8' bgs	500 ppm
BOTTOM	8' bgs	75 ppm

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

DATE January 2, 2001 PRINTED NAME Chris Rodriguez

SIGNATURE Chris Rodriguez TITLE ENVIRONMENTAL TECHNICIAN



PHONE (915) 673-7001 • 2111 BEECHWOOD • ABILENE, TX 79603  
 PHONE (505) 393-2328 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR  
 RICE OPERATING CO.  
 ATTN: JAMES STURGILL  
 122 W. TAYLOR  
 HOBBS, NM 88240  
 FAX TO:

Receiving Date: 01/02/01  
 Reporting Date: 01/04/01  
 Project Number: NOT GIVEN  
 Project Name: V-5 SIDES & BOTTOM  
 Project Location: ULV SECTION 5-T21-R36

Sampling Date: 01/02/01  
 Sample Type: SOIL  
 Sample Condition: COOL & INTACT  
 Sample Received By: B C  
 Analyzed By: BC/AH

LAB NUMBER	SAMPLE ID	GRO (C <sub>6</sub> -C <sub>10</sub> ) (mg/Kg)	DRO (>C <sub>10</sub> -C <sub>28</sub> ) (mg/Kg)	CI* (mg/Kg)
ANALYSIS DATE		01/03/01	01/03/01	01/04/01
H5489-1	V-5 BOTTOM	<50	1220	116
H5489-2	V-5 SIDES	<50	95.6	596
Quality Control		891	957	1004
True Value QC		1000	1000	1000
% Recovery		89.1	95.7	100
Relative Percent Difference		3.5	5.3	7.2

METHODS: TPH GRO & DRO: EPA SW-846 8015 M; CI\*: Std. Methods 4500-CIB  
 \*Analyses performed on 1:4 w:v aqueous extracts.

Burgess J. Cooke  
 Chemist

1/4/01  
 Date


**H5489A.XLS**  
 PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.



**ARDINAL  
LABORATORIES**

PHONE (915) 673-7001 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240




ANALYTICAL RESULTS FOR  
RICE OPERATING COMPANY  
ATTN: JAMES STURGILL  
122 W. TAYLOR  
HOBBS, NM 88240  
FAX TO:

Receiving Date: 01/02/01  
Reporting Date: 01/05/01  
Project Number: V-5 SIDES AND BOTTOM  
Project Name: V-5 SIDES AND BOTTOMS  
Project Location: ULV SECTION 5 T21 R36

Sampling Date: 01/02/01  
Sample Type: SOIL  
Sample Condition: COOL, INTACT  
Sample Received By: BC-HOBBS  
Analyzed By: JA

LAB NUMBER	SAMPLE ID	BENZENE (mg/Kg)	TOLUENE (mg/Kg)	ETHYL BENZENE (mg/Kg)	TOTAL XYLENES (mg/Kg)
ANALYSIS DATE		01/04/01	01/04/01	01/04/01	01/04/01
H5489-1	V-5 BOTTOM	<0.002	<0.002	<0.002	<0.006
H5489-2	V-5 SIDES	<0.002	<0.002	<0.002	<0.006
Quality Control		0.092	0.096	0.087	0.262
True Value QC		0.100	0.100	0.100	0.300
% Accuracy		92	96	87	87
Relative Percent Difference		4.9	2.8	2.4	2.3

METHOD: EPA SW 846-8020, 5030, Gas Chromatography

  
\_\_\_\_\_  
Chemist

1-5-01  
\_\_\_\_\_  
Date

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.

# CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

Page \_\_\_\_\_ of \_\_\_\_\_

## CARDINAL LABORATORIES, INC.

2111 Beechwood, Abilene, TX 79603 101 East Marland, Hobbs, NM 88240  
 (915) 673-7001 Fax (915) 673-7020 (505) 393-2326 Fax (505) 393-2476

<b>BILL TO</b>		<b>ANALYSIS REQUEST</b>	
Company Name: <i>Rice Operating Company</i>		P.O. #:	
Project Manager: <i>James Stegall</i>		Company:	
Address: <i>122 W. Taylor</i>		Attn:	
City: <i>Nobbs</i> State: <i>TX</i> Zip: <i>78240</i>		Address:	
Phone #: <i>3488174</i> Fax #:		City:	
Project #: <i>V-5 sides and Bottoms</i>		State:	
Project Name: <i>V-5 sections T 2, R 36</i>		Phone #:	
Project Location: <i>UHV Section 5 T 2, R 36</i>		Fax #:	
Sampler Name: <i>James Stegall</i>			

FOR LAB USE ONLY	
<p>Lab I.D. <b>Sample I.D.</b></p> <p><i>4584-1 V-5 Bottom</i></p> <p><i>-2 V-5 sides</i></p>	<p>MATRIX</p> <p>GROUNDWATER <input type="checkbox"/></p> <p>WASTEWATER <input type="checkbox"/></p> <p>SOIL <input checked="" type="checkbox"/></p> <p>CRUDE OIL <input type="checkbox"/></p> <p>SLUDGE <input type="checkbox"/></p> <p>OTHER: <input type="checkbox"/></p> <p>ACID/BASE: <input type="checkbox"/></p> <p>ICE / COOL <input type="checkbox"/></p> <p>OTHER: <input type="checkbox"/></p> <p>PRESERV</p> <p>DATE: <i>11/01/01</i></p> <p>TIME: <i>11:00 AM</i></p>
<p>PLEASE NOTE: Liability and Damages: Cardinal's liability and that's exclusive remedy for any claim arising whether based in contract or tort, shall be limited to the amount paid by the client for the analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within 30 days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated measure or otherwise.</p>	
<p>Sampler Relinquished: <i>James Stegall</i> Date: _____ Time: _____</p> <p>Received By: _____ Date: <i>01/02/01</i> Time: <i>4:00</i></p> <p>Relinquished By: _____ Received By: (Lab Staff) <i>James Stegall</i></p>	
<p>Delivered By: (Circle One)</p> <p>Sampler - UPS - Bus - Other:</p>	
<p>Phone Result: <input type="checkbox"/> Yes <input type="checkbox"/> No Add'l Phone #:</p> <p>Fax Result: <input type="checkbox"/> Yes <input type="checkbox"/> No Add'l Fax #:</p> <p>REMARKS:</p>	

† Cardinal cannot accept verbal changes. Please fax written changes to 505-393-2476.

# Sundance Services, Inc.

P.O. Box 1737 ★ Eunice, NM 88231  
(505) 394-2511

NC 36866

LEASE OPERATOR/SHIPPER/COMPANY: None

LEASE NAME: FAVE OCT 4-5 692

TRANSPORTER COMPANY: RXE TIME: \_\_\_\_\_ AM/PM

DATE: 1-23-01 VEHICLE NO.: 1000 DRIVER NO.:

CHARGE TO: None

## TYPE OF MATERIAL

- |   |  |  |
|---|--|--|
| <input type="checkbox"/> Production Water | <input type="checkbox"/> Drilling Fluids     | <input type="checkbox"/> Completion Fluids |
| <input type="checkbox"/> Tank Bottoms     | <input type="checkbox"/> Contaminated soil   | <input type="checkbox"/> C-117 No.: _____  |
| <input type="checkbox"/> Other Material:  | <input type="checkbox"/> BS&W Content: _____ |  |

Description: oil cut

VOLUME OF MATERIAL  BBLs. \_\_\_\_\_ :  YARD 12 :  \_\_\_\_\_

AS A CONDITION TO SUNDANCE SERVICES, INC.'S ACCEPTANCE OF THE MATERIALS SHIPPED WITH THIS JOB TICKET, OPERATOR/SHIPPER REPRESENTS AND WARRANTS THAT THE WASTE MATERIAL SHIPPED HERewith IS MATERIAL EXEMPT FROM THE RESOURCE, CONSERVATION AND RECOVERY ACT OF 1976, AS AMENDED FROM TIME TO TIME, 40 U.S.C. § 6901, et seq., THE NM HEALTH AND SAF. CODE § 361.001, et seq., AND REGULATIONS RELATED THERETO, BY VIRTUE OF THE EXEMPTION AFFORDED DRILLING FLUIDS, PRODUCED WATERS, AND OTHER WASTE ASSOCIATED WITH THE EXPLORATION, DEVELOPMENT OR PRODUCTION OF CRUDE OIL OR NATURAL GAS OR GEOTHERMAL ENERGY.

ALSO AS A CONDITION TO SUNDANCE SERVICES, INC.'S ACCEPTANCE OF THE MATERIALS SHIPPED WITH THIS JOB TICKET, TRANSPORTER REPRESENTS AND WARRANTS THAT ONLY THE MATERIAL DELIVERED BY OPERATOR/SHIPPER TO TRANSPORTER IS NOW DELIVERED BY TRANSPORTER TO SUNDANCE SERVICES, INC.'S FACILITY FOR DISPOSAL.

*THIS WILL CERTIFY that the above Transporter loaded the material represented by this Transporter Statement at the above described location, and that it was tendered by the above described shipper. This will certify that no additional materials were added to this load, and that the material was delivered without incident.*

DRIVER: Luis S. Ojeda  
(SIGNATURE)

FACILITY REPRESENTATIVE: \_\_\_\_\_  
(SIGNATURE)

**RICE OPERATING COMPANY  
JUNCTION BOX FINAL REPORT**

**BOX LOCATION**

SWD SYSTEM	JUNCTION	UNIT	SECTION	TOWNSHIP	RANGE	COUNTY	BOX DIMENSIONS - FEET		
							Length	Width	Depth
EME	V-5	V	5	21S	36E	LEA	4'	4'	3'

LAND TYPE: \_\_\_\_\_ STATE X FEE LANDOWNER \_\_\_\_\_ OTHER \_\_\_\_\_

Depth to Groundwater 150'-200' feet NMOCD SITE ASSESSMENT RANKING SCORE: 0

Date Started 01/02/2001 Date Completed 01/02/2001 OCD Witness NONE

Soil Excavated 12 cubic yards Excavation Length 8' Width 8' Depth 5' feet

Soil Disposed 12 cubic yards Offsite Facility Sundance Disposal Location E.M.E.

**FINAL ANALYTICAL RESULTS:** Sample Date 01/02/2001 Sample Depth 5' bgs

Procure 5-point composite sample of bottom and 4-point composite sample of sidewalls. TPH, BTEX and Chloride laboratory test results completed by using an approved lab and testing procedures pursuant to NMOCD guidelines.

Sample Location	Benzene mg/kg	Toluene mg/kg	Ethyl Benzene mg/kg	Total Xylenes mg/kg	GRO mg/kg	DRO mg/kg	Chlorides mg/kg
SIDEWALLS	<0.002	<0.002	<0.002	<0.006	<50	95.6	596
BOTTOM	<0.002	<0.002	<0.002	<0.006	<50	1220	116

General Description of Remedial Action: Jct box is gone off of the main line.

The main line is still active. All impacted soil was hauled off to Sundance Disposal Facility and replaced with clean backfill. A clay barrier was installed followed by water tight junction then backfilled. Results did not exceed the NMOCD guidelines.

**CHLORIDE FIELD TESTS**

LOCATION	DEPTH	Cl
SIDEWALLS	4'-8' bgs	500 ppm
BOTTOM	8' bgs	75 ppm

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

DATE 02-Jan-01 PRINTED NAME Chris Rodriguez  
SIGNATURE *Chris Rodriguez* TITLE ENVIRONMENTAL TECHNICIAN



PHONE (915) 673-7001 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (505) 393-2328 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR  
RICE OPERATING CO.  
ATTN: JAMES STURGILL  
122 W. TAYLOR  
HOBBS, NM 88240  
FAX TO:

Receiving Date: 01/02/01  
Reporting Date: 01/04/01  
Project Number: NOT GIVEN  
Project Name: V-5 SIDES & BOTTOM  
Project Location: ULV SECTION 5-T21-R36

Sampling Date: 01/02/01  
Sample Type: SOIL  
Sample Condition: COOL & INTACT  
Sample Received By: B C  
Analyzed By: BC/AH

LAB NUMBER SAMPLE ID	GRO (C <sub>6</sub> -C <sub>10</sub> ) (mg/Kg)	DRO (>C <sub>10</sub> -C <sub>28</sub> ) (mg/Kg)	CI* (mg/Kg)
ANALYSIS DATE	01/03/01	01/03/01	01/04/01
H5489-1 V-5 BOTTOM	<50	1220	116
H5489-2 V-5 SIDES	<50	95.6	596
Quality Control	891	957	1004
True Value QC	1000	1000	1000
% Recovery	89.1	95.7	100
Relative Percent Difference	3.5	5.3	7.2

METHODS: TPH GRO & DRO: EPA SW-846 8015 M; CI: Std. Methods 4500-CI<sub>B</sub>

\*Analyses performed on 1:4 w:v aqueous extracts.

*Burgess J. Coche*  
Chemist

1/4/01  
Date


H5489A.XLS  
PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.



**ARDINAL  
LABORATORIES**

PHONE (915) 673-7001 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240




ANALYTICAL RESULTS FOR  
RICE OPERATING COMPANY  
ATTN: JAMES STURGILL  
122 W. TAYLOR  
HOBBS, NM 88240  
FAX TO:

Receiving Date: 01/02/01  
Reporting Date: 01/05/01  
Project Number: V-5 SIDES AND BOTTOM  
Project Name: V-5 SIDES AND BOTTOMS  
Project Location: ULV SECTION 5 T21 R36

Sampling Date: 01/02/01  
Sample Type: SOIL  
Sample Condition: COOL, INTACT  
Sample Received By: BC-HOBBS  
Analyzed By: JA

LAB NUMBER	SAMPLE ID	BENZENE (mg/Kg)	TOLUENE (mg/Kg)	ETHYL BENZENE (mg/Kg)	TOTAL XYLENES (mg/Kg)
ANALYSIS DATE		01/04/01	01/04/01	01/04/01	01/04/01
H5489-1	V-5 BOTTOM	<0.002	<0.002	<0.002	<0.006
H5489-2	V-5 SIDES	<0.002	<0.002	<0.002	<0.006
Quality Control		0.092	0.096	0.087	0.262
True Value QC		0.100	0.100	0.100	0.300
% Accuracy		92	96	87	87
Relative Percent Difference		4.9	2.8	2.4	2.3

METHOD: EPA SW 846-8020, 5030, Gas Chromatography

  
\_\_\_\_\_  
Chemist

1-5-01  
\_\_\_\_\_  
Date

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.

H5489SHOBBSRICEBTEXONLY



# CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

## CARDINAL LABORATORIES, INC.

2111 Beechwood, Abilene, TX 79603 101 East Marland, Hobbs, NM 88240  
(915) 673-7001 Fax (915) 673-7020 (505) 393-2326 Fax (505) 393-2476

Page \_\_\_\_\_ of \_\_\_\_\_

Company Name: <u>Rice Operating Company</u>		<b>BILL TO</b>		ANALYSIS REQUEST																	
Project Manager: <u>James Stevig</u>		P.O. #:																			
Address: <u>122 W. Taylor</u>		Company:																			
City: <u>Hobbs</u> State: <u>NM</u> Zip: <u>88240</u>		Attn:																			
Phone #: <u>3438174</u> Fax #:		Address:																			
Project #: <u>V-5 sides and Bottoms</u>		City:																			
Project Name: <u>V-5 Sides and Bottoms</u>		State:																			
Project Location: <u>UV Section 5 T21 R 36</u>		Phone #:																			
Sampler Name: <u>James Stevig</u>		Fax #:																			
FOR LAB USE ONLY																					
Lab I.D.		Sample I.D.		PRESERV		SAMPLING		DATE		TIME											
1584-1		V-5 BOTTOM		OTHER:		ICE / COOL		2/10/01													
-2		V-5 sides		ACID/BASE:		OTHER:															
				SLUDGE		GROUNDWATER															
				CRUDE OIL		WASTEWATER															
				SOIL		# CONTAINERS															
				WASTEWATER		(GRAB OR (COMP.															

Handwritten: KTX 12/8/01

PLEASE NOTE: Liability and insurance. Cardinal's liability and client's insurance remedy for any claim arising whether based in contract or tort, shall be limited to the amount paid by the client for the analysis. All claims including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within 30 days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated remedies or otherwise.

Sampler Relinquished By: James Stevig Date: \_\_\_\_\_ Time: \_\_\_\_\_

Relinquished By: \_\_\_\_\_ Date: 5/10/01 Time: 4:00

Delivered By: (Circle One) UPS - Bus - Other: \_\_\_\_\_

Sampler - UPS - Bus - Other: \_\_\_\_\_

Received By: (Lab Staff) James Stevig Checked By: (Initials) \_\_\_\_\_

Phone Result:  Yes  No Add'l Phone #: \_\_\_\_\_

Fax Result:  Yes  No Add'l Fax #: \_\_\_\_\_

REMARKS:

† Cardinal cannot accept verbal changes. Please fax written changes to 505-393-2476.

# Sundance Services, Inc.

P.O. Box 1737 ★ Eunice, NM 88231  
(505) 394-2511

NC 36866

LEASE OPERATOR/SHIPPER/COMPANY: Nice

LEASE NAME: EMERGENCY 692

TRANSPORTER COMPANY: RXE TIME: \_\_\_\_\_ AM/PM

DATE: 1-23-01 VEHICLE NO.: 1000 DRIVER NO.:

CHARGE TO: Nice

## TYPE OF MATERIAL

- |   |  |  |
|---|--|--|
| <input type="checkbox"/> Production Water | <input type="checkbox"/> Drilling Fluids     | <input type="checkbox"/> Completion Fluids |
| <input type="checkbox"/> Tank Bottoms     | <input type="checkbox"/> Contaminated soil   | <input type="checkbox"/> C-117 No.:        |
| <input type="checkbox"/> Other Material:  | <input type="checkbox"/> BS&W Content: _____ |  |

Description: oil cut

VOLUME OF MATERIAL  BBLs. \_\_\_\_\_ :  YARD 12 :  \_\_\_\_\_

AS A CONDITION TO SUNDANCE SERVICES, INC.'S ACCEPTANCE OF THE MATERIALS SHIPPED WITH THIS JOB TICKET, OPERATOR/SHIPPER REPRESENTS AND WARRANTS THAT THE WASTE MATERIAL SHIPPED HERewith IS MATERIAL EXEMPT FROM THE RESOURCE, CONSERVATION AND RECOVERY ACT OF 1976, AS AMENDED FROM TIME TO TIME, 40 U.S.C. § 6901, et seq., THE NM HEALTH AND SAF. CODE § 361.001, et seq., AND REGULATIONS RELATED THERETO, BY VIRTUE OF THE EXEMPTION AFFORDED DRILLING FLUIDS, PRODUCED WATERS, AND OTHER WASTE ASSOCIATED WITH THE EXPLORATION, DEVELOPMENT OR PRODUCTION OF CRUDE OIL OR NATURAL GAS OR GEOTHERMAL ENERGY.

ALSO AS A CONDITION TO SUNDANCE SERVICES, INC.'S ACCEPTANCE OF THE MATERIALS SHIPPED WITH THIS JOB TICKET, TRANSPORTER REPRESENTS AND WARRANTS THAT ONLY THE MATERIAL DELIVERED BY OPERATOR/SHIPPER TO TRANSPORTER IS NOW DELIVERED BY TRANSPORTER TO SUNDANCE SERVICES, INC.'S FACILITY FOR DISPOSAL.

*THIS WILL CERTIFY that the above Transporter loaded the material represented by this Transporter Statement at the above described location, and that it was tendered by the above described shipper. This will certify that no additional materials were added to this load, and that the material was delivered without incident.*

DRIVER: Luis Saldano  
(SIGNATURE)

FACILITY REPRESENTATIVE: [Signature]  
(SIGNATURE)