

1R - 427 - 127

REPORTS

DATE:

2-14-2001

**RICE OPERATING COMPANY
JUNCTION BOX FINAL REPORT**

427-127

BOX LOCATION

SWD SYSTEM	JUNCTION	UNIT	SECTION	TOWNSHIP	RANGE	COUNTY	BOX DIMENSIONS - FEET		
EME	N-6	N	6	21S	36E	LEA	Length 5'	Width 5'	Depth 4'

LAND TYPE: BLM ☐ STATE ☒ FEE LANDOWNER _____ OTHER _____

Depth to Groundwater 157 feet NMOCD SITE ASSESSMENT RANKING SCORE: 0

Date Started 9-29-01 Date Completed 12-7-00 OCD Witness NONE

Soil Excavated _____ cubic yards Excavation Length 5' Width 5' Depth 4' feet

Soil Disposed _____ cubic yards Offsite Facility _____ Location _____

FINAL ANALYTICAL RESULTS: Sample Date 11-20-00 Sample Depth 6'

Procure 5-point composite sample of bottom and 4-point composite sample of sidewalls. TPH, BTEX and Chloride laboratory test results completed by using an approved lab and testing procedures pursuant to NMOCD guidelines.

Sample Location	Benzene ma/ka	Toluene ma/ka	Ethyl Benzene ma/ka	Total Xylenes ma/ka	GRO ma/ka	DRO ma/ka	Chlorides ma/ka
SIDEWALLS	<0.005	<0.005	<0.005	<0.005	<50	256	427
BOTTOM	<0.005	<0.005	<0.005	<0.005	<50	80.6	259

General Description of Remedial Action:

A CLEAN BOX THAT DID NOT REQUIRE ANY ADDITION ACTION ON IT.

CHLORIDE FIELD TESTS

LOCATION	DEPTH	mg/kg
SIDEWALLS	2'	400
BOTTOM	6'	170

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

DATE FEBRUARY 14, 2001 PRINTED NAME JAMES STURGILL

SIGNATURE *James Sturgill* TITLE ENVIRONMENTAL TECHNICIAN



PHONE (915) 873-7001 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (805) 383-2328 • 101 E. MARLAND • HOBBS, NM 88240


ANALYTICAL RESULTS FOR
RICE OPERATING CO.
ATTN: JAMES STURGILL
122 W. TAYLOR
HOBBS, NM 88240
FAX TO:

Receiving Date: 11/14/00
Reporting Date: 11/16/00
Project Number: NOT GIVEN
Project Name: N-6 EME
Project Location: UN SEC 6-T21S-R36E

Sampling Date: 11/14/00
Sample Type: SOIL
Sample Condition: COOL & INTACT
Sample Received By: AH
Analyzed By: BC

LAB NO.	SAMPLE ID	BENZENE (mg/Kg)	TOLUENE (mg/Kg)	ETHYL BENZENE (mg/Kg)	TOTAL XYLENES (mg/Kg)
ANALYSIS DATE		11/15/00	11/15/00	11/15/00	11/15/00
H5342-1	N-6 SIDE EME	<0.005	<0.005	<0.005	<0.015
H5342-2	N-6 BOTTOM EME	<0.005	<0.005	<0.005	<0.015
Quality Control		0.094	0.095	0.087	0.266
True Value QC		0.100	0.100	0.100	0.300
% Recovery		93.8	94.7	87.2	88.6
Relative Percent Difference		1.4	3.8	0.6	2.8

METHOD: EPA SW-846 8260


Chemist

11/16/00
Date

H5342B.XLS

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.



ARDINAL LABORATORIES

PHONE (815) 873-7001 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR
RICE OPERATING CO.
ATTN: JAMES STURGILL
122 W. TAYLOR
HOBBS, NM 88240
FAX TO:


Receiving Date: 11/14/00
Reporting Date: 11/15/00
Project Number: NOT GIVEN
Project Name: N-6 EME
Project Location: UN-SEC 6-T21S-R36E

Sampling Date: 11/14/00
Sample Type: SOIL
Sample Condition: COOL & INTACT
Sample Received By: AH
Analyzed By: BC/AH

LAB NUMBER	SAMPLE ID	GRO (C ₅ -C ₁₀) (mg/Kg)	DRO (C ₁₀ -C ₂₈) (mg/Kg)	CI [*] (mg/Kg)
ANALYSIS DATE		11/14/00	11/14/00	11/15/00
H5342-1	N-6 SIDE EME	<50	256	427
H5342-2	N-6 BOTTOM EME	<50	80.6	259
Quality Control		787	804	954
True Value QC		800	800	1000
% Recovery		98.3	100	95.4
Relative Percent Difference		7.7	0.9	4.9

METHODS: TPH-GRO & DRO: EPA SW-846 8015 M; CI: Std. Methods 4500-CI B

*Analyses performed on 1:4 w:v aqueous extracts.


 Chemist


 Date

H5342A.XLS

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.

2111 Beechwood, Abilene, TX 79603 101 East Marland, Hobbs, NM 88240
(915) 673-7001 Fax (915) 673-7020 (505) 393-2326 Fax (505) 393-2476

Page of [illegible]

+ Cardinal cannot accept verbal changes. Please fax written changes to 505-393-2476.

Field (089)

State of New Mexico
Environment Department
Radiation Licensing and Registration
P. O. Box 26110
Santa Fe, New Mexico 87502
(505) 827-1557

Temporary Job Site Notification Form

(Required BEFORE Work Begins)

Part I - Licensee Performing Job-Site Activity

Name: RICE OPERATING COMPANY License # NO338-01
Street Address: 122 WEST TAYLOR City: HOBBS
State: NEW MEXICO Zip: 88240 Phone: (505) 393-9174
FAX (505) 379-1471

Part II - Customer and Job Site Information

Name: RICE OPERATING COMPANY
Contact Person & Title: JOHN L. MOODY R.S.O. Phone: (505) 393-9174
Job Site Location (give directions to site): UNIT LTR. N SEC. 6 T21 S R36 E.
ALL LOCATIONS ARE IN THE OILFIELD. CALL OUR OFFICE AND WE WILL TAKE YOU TO THE
LOCATION. E.M.E. SWA
Describe Site Specific Activity: REMOVE NORM FROM PIPELINE JUNCTION BOXES

Starting Date: 8-00 Projected Completion: 11-00

Local Ordinance or Permit Required? NO

Have they been obtained? List:

Part III - Storage

If storage site is different from the job site location give the location and directions to the site. (Attach a map if street address is not available).

NORM WILL BE STORED IN OUR H-20 STORAGE AREA. NORM WILL BE SHIPPED TO DISPOSAL
IN ROLL OFF CONTAINERS.

Describe storage conditions. (Security, storage are construction, signs used and locations, etc.)

FENCED WITH LOCKED GATES. RADIATION STORAGE SIGNS FENCE AND ALL GATES.
LOCATION IS IN A REMOTE AREA.

Signature of Requester:

John L. Plough RSO.

Date: *8-7-00*

(C)