

Virgilio Cocianni
Remediation Manager

Schlumberger Technology Corporation
121 Industrial Drive
Sugar Land, TX 77478
Tel: (281) 285-4747

March 28, 2016

Mr. Bradford Billings
Environmental Bureau
New Mexico Oil Conservation Division
1220 South St. Francis Drive
Santa Fe, New Mexico 87505

Re: 2015 Annual Groundwater Monitoring Report, Former Dowell Schlumberger Facility, 507 East Richey Avenue, Artesia, Eddy County, New Mexico. Discharge Permit GW-114.

Dear Mr. Billings,

Please find the Annual Groundwater Monitoring Report for the Former Dowell Schlumberger Facility in Artesia, New Mexico, on the enclosed CD. The report presents recommendations for modifications to the monitoring program and abandonment of unused monitoring wells. Schlumberger Technology Corporation kindly requests NMOCD review and concurrence with these recommendations so that the modified sampling program can be implemented during the April 2016 semiannual sampling event.

The Discharge Permit GW-114 renewal application was submitted to NMOCD on July 15, 2013, and Schlumberger Technology Corporation also requests a status update regarding the application review.

Should you have any questions regarding the enclosed submittal or the Discharge Permit renewal, please contact me at (281) 285-4747. I can also be reached by e-mail at cocianni-v@slb.com.

I look forward to our continued work with you.

Sincerely,



V. COCIANNI

Virgilio Cocianni
Remediation Manager

Enclosure

c: Jim Strunk, The Dow Chemical Company (1 hardcopy and 1 CD)
Cathy Barnett, CH2M
Jeffrey Minchak, CH2M