

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

| | |
|----------------|---------------|
| Incident ID | NRM2002459486 |
| District RP | |
| Facility ID | |
| Application ID | |

Release Notification

Responsible Party

06LWD-191211-C-1410

| | |
|--|--------------------------------|
| Responsible Party ConocoPhillips Company | OGRID 217817 |
| Contact Name Gustavo Fejervary | Contact Telephone 432/210-7037 |
| Contact email g.fejervary@cop.com | Incident # (assigned by OCD) |
| Contact mailing address 5735 SW 7000 Andrews, TX 79714 | |

Location of Release Source

Latitude 32.783268 Longitude -103.478775
(NAD 83 in decimal degrees to 5 decimal places)

| | |
|---------------------------------|----------------------|
| Site Name EVGSAU 0546-123 | Site Type flowline |
| Date Release Discovered 12/6/19 | API# (if applicable) |

| Unit Letter | Section | Township | Range | County |
|-------------|---------|----------|-------|--------|
| B | 05 | 18S | 35E | Lea |

Surface Owner: ☒ State ☐ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

| | | |
|--|--|--|
| <input checked="" type="checkbox"/> Crude Oil | Volume Released (bbls) 4.31 | Volume Recovered (bbls) 3.74 |
| <input checked="" type="checkbox"/> Produced Water | Volume Released (bbls) 12.93 | Volume Recovered (bbls) 11.25 |
| | Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l? | <input type="checkbox"/> Yes <input type="checkbox"/> No |
| <input type="checkbox"/> Condensate | Volume Released (bbls) | Volume Recovered (bbls) |
| <input type="checkbox"/> Natural Gas | Volume Released (Mcf) | Volume Recovered (Mcf) |
| <input type="checkbox"/> Other (describe) | Volume/Weight Released (provide units) | Volume/Weight Recovered (provide units) |




Cause of Release Flowline rupture

State of New Mexico
Oil Conservation Division

| | |
|----------------|---------------|
| Incident ID | NRM2002459486 |
| District RP | |
| Facility ID | |
| Application ID | |

| | |
|--|---|
| <p>Was this a major release as defined by 19.15.29.7(A) NMAC?</p> <p><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p> | <p>If YES, for what reason(s) does the responsible party consider this a major release?</p> |
| <p>If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?</p> | |

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

| | | | | | | | | | |
|---|---|--|---|---|-----------------------|-----------------------------------|--------------------------------|-----------------------------------|-------------------------|
| <p><input checked="" type="checkbox"/> The source of the release has been stopped.</p> <p><input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment.</p> <p><input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.</p> <p><input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.</p> <p>If all the actions described above have <u>not</u> been undertaken, explain why:</p> <p>Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.</p> <p>I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.</p> <table border="0"><tr><td>Printed Name: <u>Gustavo Fejervary</u></td><td>Title: <u>Environmental Coordinator</u></td></tr><tr><td>Signature: <u></u></td><td>Date: <u>12/11/19</u></td></tr><tr><td>email: <u>g.fejervary@cop.com</u></td><td>Telephone: <u>432/210-7037</u></td></tr></table> <p><u>OCD Only</u></p> <table border="0"><tr><td>Received by: <u>Ramona Marcus</u></td><td>Date: <u>01/24/2020</u></td></tr></table> | | Printed Name: <u>Gustavo Fejervary</u> | Title: <u>Environmental Coordinator</u> | Signature: <u></u> | Date: <u>12/11/19</u> | email: <u>g.fejervary@cop.com</u> | Telephone: <u>432/210-7037</u> | Received by: <u>Ramona Marcus</u> | Date: <u>01/24/2020</u> |
| Printed Name: <u>Gustavo Fejervary</u> | Title: <u>Environmental Coordinator</u> | | | | | | | | |
| Signature: <u></u> | Date: <u>12/11/19</u> | | | | | | | | |
| email: <u>g.fejervary@cop.com</u> | Telephone: <u>432/210-7037</u> | | | | | | | | |
| Received by: <u>Ramona Marcus</u> | Date: <u>01/24/2020</u> | | | | | | | | |

| L48 Spill Volume Estimate Form | | | | | | | | | |
|--|--------------|---|-------------|-------------------------------|--------------------------------------|--|---|--|--|
| Facility Name & Number: | | EVGSAU 0546-123 | | | | | | | |
| Asset Area: | | SENM (Buckeye) | | | | | | | |
| Release Discovery Date & Time: | | 9:00 A.M. 12/6/19 | | | | | | | |
| Release Type: | | Oil Mixture | | | | | | | |
| Provide any known details about the event: | | Flowline leak. 15 bbls picked up via vacuum truck | | | | | | | |
| Spill Calculation - Subsurface Spill - Rectangle | | | | | | | | | |
| On Pad - 10.5%; Off Pad - 15.12% soil spilled-fluid saturation factor; if No, use factors above. | | | | | | | | | |
| Yes, On Pad - 8%; Off Pad - 13.57% soil spilled-fluid saturation factor | | | | | | | | | |
| Convert Irregular shape into a series of rectangles | Length (ft.) | Width (ft.) | Depth (in.) | Soil Spilled-Fluid Saturation | Estimated volume of each area (bbl.) | Total Estimated Volume of Spill (bbl.) | Percentage of Oil if Spilled Fluid is a Mixture | Total Estimated Volume of Spilled Oil (bbl.) | Total Estimated Volume of Spilled Liquid other than Oil (bbl.) |
| Rectangle A | 15.0 | 18.0 | 1.50 | 15.12% | 6.008 | 0.908 | 25.00% | 0.227 | 0.681 |
| Rectangle B | 12.0 | 6.0 | 1.50 | 15.12% | 1.602 | 0.242 | 25.00% | 0.061 | 0.182 |
| Rectangle C | 27.0 | 12.0 | 1.50 | 15.12% | 7.209 | 1.090 | 25.00% | 0.273 | 0.818 |
| Rectangle D | | | | | 0.000 | 0.000 | 0.00% | 0.000 | 0.000 |
| Rectangle E | | | | | 0.000 | 0.000 | 0.00% | 0.000 | 0.000 |
| Rectangle F | | | | | 0.000 | 0.000 | | 0.000 | 0.000 |
| Rectangle G | | | | | 0.000 | 0.000 | | 0.000 | 0.000 |
| Rectangle H | | | | | 0.000 | 0.000 | | 0.000 | 0.000 |
| Rectangle I | | | | | 0.000 | 0.000 | | 0.000 | 0.000 |
| Rectangle J | | | | | 0.000 | 0.000 | | 0.000 | 0.000 |
| Total Volume Release: | | | | | 2.241 | 0.000 | | 0.560 | 1.680 |

