

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Incident ID	NRM2006950449
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party: Black River Trucking and HotShot Services	OGRID: None 329769
Contact Name: Joel Longoria	Contact Telephone: 575-302-9220
Contact email: jlongoria09@gmail.com	Incident # (assigned by OCD) : NRM2006950449
Contact mailing address: 25 N Nicholas Rd / P.O Box 126 Malaga, NM 88263	

Location of Release Source

Latitude 32.061281°

Longitude -104.370914°

(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Pine Springs 2 State SWD #1	Site Type: Battery
Date Release Discovered: 11/21/2019	API# (if applicable)

Unit Letter	Section	Township	Range	County
D	11	26S	25E	Eddy

Surface Owner: State Federal Tribal Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls): 25 bbl	Volume Recovered (bbls): 0 bbl
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls): 24 bbl	Volume Recovered (bbls): 0 bbl
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release: A transport vehicle illegally dumped 49 bbls of oily substance to the lease road leading to the battery. A vac truck was dispatched on discovery of the release to remove free standing fluids. Black River Trucking and HotShot Services, in conjunction with COG Operating LLC, will evaluate the site to determine if we may commence remediation immediately or delineate any possible impact from the release and will present a remediation workplan to the NMOCD for approval prior to any significant remediation activities.

State of New Mexico
Oil Conservation Division

Page 2

Incident ID	NRM2006950449
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? The volume released was greater than 25 bbls.
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? No	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: 	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Joel Longoria</u>	Title: <u>Safety Coordinator</u>
Signature: <u>[Handwritten Signature]</u>	Date: <u>3/11/2020</u>
email: <u>jlongoria199@gmail.com</u>	Telephone: <u>575-302-9220</u>
<u>OCD Only</u>	
Received by: <u>Ramona Marcus</u>	Date: <u>3/12/2020</u>